



# LIFTING MACHINERY CONSULTANTS & SURVEYORS


PINE RIDGE, ERCALL HEATH, NR. NEWPORT, SHROPSHIRE. TEL:01952 550539

## Report of Examination Of Chains, Ropes & Lifting Tackle

| Contract No. 1022.  |  | Report No. 1022/34/24.            |
|---|--|-----------------------------------|
| Name of Occupier. Prism Lighting,   |  |                                   |
| Address. Unit 5A, Hampton Heath Industrial Estate, Hampton Heath, Malpas, Cheshire. |  |                                   |
| Item No.  | Distinguishing number or mark and description<br>Defects found and steps to remedy them. General remarks.                                    | Safe Working Load<br>CODE YELLOW. |
| 1.  | 60 5/8" D Shackles were examined and found to be in good order.  | 3 ¼ Ton                           |
| 2.  | The following numbered Spanset Slings x 2 M Circ were examined and found to be in good order:<br>07-31844, 07-31821, 07-31852, 04-2036435.   | 2 Ton                             |
| 3.  | The following numbered Spanset Slings x 4 M Circ were examined and found to be in good order:<br>000351052, 000351069, 000351086, 000351081. | 2 Ton                             |
| 4.  | 4 Master Links were examined and found to be in good order.  | 2.0 Ton                           |
| 5.  | The following numbered 10ft Steel Wire Ropes were examined and found to be in good order:<br>PR370, PR391, PR365, PR358.                     | 1000 KG                           |
| 6.  | The following numbered 20ft Steel Wire Ropes were examined and found to be in good order:<br>EWR26213/1, PR420, PR417, EWR26213/2.           | 1.5 Ton                           |
| 7.  | The following numbered 30ft Steel Wire Ropes were examined and found to be in good order:<br>PR609, EWR50683/13, EWR50683/22, EWR50683/20.   | 1000 KG                           |
|   | Latest date for completion of next thorough Inspection:<br>Date of last previous thorough Inspection:  | 2-3-2012.<br>21-3-2011.           |

I certify that on 2<sup>nd</sup> September 2011. I examined the above plant and the above is an accurate report of that examination.

INSPECTIONS IN ACCORDANCE WITH /LIFTING OPERATIONS AND  
LIFTING EQUIPMENT REGULATIONS 1998

Inspecting Engineer.....  
Signature..........Robert C.C Healey.  
Qualification Consultant Engineer  
Lifting Machinery Consultants & Surveyors



# LIFTING MACHINERY CONSULTANTS & SURVEYORS

PINE RIDGE, ERCALL HEATH, NR. NEWPORT, SHROPSHIRE. TEL: 01952 550539

## Report Of Examination Of Lifting Machine


|                    |                       |
|--------------------|-----------------------|
| Contract No. 1022. | Report No. 1022/34/2. |
|--------------------|-----------------------|

|  |
|--|
| Contact Name Prism Lighting,<br>Address Unit 5A, Hampton Heath Industrial Estate, Hampton Heath, Malpas, Cheshire. |
|--|

| Item No | Distinguishing number or mark and description<br>(a) Defects effecting safe working and repairs required immediately or within a specified time.<br>(b) Other defects, their remedies and observations. | Safe Working Load.       |
|---------|---|--------------------------|
| 1.      | PR 1 - 06322. Pfaff Spur Geared Chain Block.<br><br>(a) None.<br>(b) None.  | 1 Ton.                   |
| 2.      | PR 2 - 06337. Pfaff Spur Geared Chain Block.<br><br>(a) None.<br>(b) None.  | 1 Ton.                   |
| 3.      | PR 3 - 06326. Pfaff Spur Geared Chain Block.<br><br>(a) None.<br>(b) None.  | 1 Ton.                   |
| 4.      | PR 4 - 06334. Pfaff Spur Geared Chain Block.<br><br>(a) None.<br>(b) None.  | 1 Ton.                   |
| 5.      | PR 5. Kito Spur Geared Chain Block.<br><br>(a) None.<br>(b) None.   | 1 Ton.                   |
|         | Latest date for completion of next thorough inspection:<br>Date of last previous through inspection:  | 23-3-2012.<br>30-3-2010. |

Inspections in accordance with LIFTING OPERATIONS AND LIFTING EQUIPMENT REGULATIONS 1998.

I certify that on 23<sup>rd</sup> March 2011. I carried out a thorough examination of all accessible parts of the lifting machine and above is an accurate report of such examination.

Signature...  .....Robert C.C Healey.  
Qualification Consultant Engineer  
Lifting Machinery Consultants & Surveyors

# LIFTING MACHINERY CONSULTANTS & SURVEYORS

PINE RIDGE, ERCALL HEATH, NR. NEWPORT, SHROPSHIRE. TEL: 01952 550539

## Report Of Examination Of Lifting Machine


|                    |                       |
|--------------------|-----------------------|
| Contract No. 1022. | Report No. 1022/34/3. |
|--------------------|-----------------------|

|  |
|--|
| Contact Name Prism Lighting,<br>Address Unit 5A, Hampton Heath Industrial Estate, Hampton Heath, Malpas, Cheshire. |
|--|

| Item No | Distinguishing number or mark and description<br>(a) Defects effecting safe working and repairs required immediately or within a specified time.<br>(b) Other defects, their remedies and observations. | Safe Working Load.       |
|---------|---|--------------------------|
| 1.      | PR 6. Kito Spur Geared Chain Block.<br>(a) None.<br>(b) None.   | 1 Ton.                   |
| 2.      | 50264. Jet Spur Geared Chain Block.<br>(a) None.<br>(b) None.   | ½ Ton.                   |
| 3.      | C.4522. Pfaff Spur Geared Chain Block.<br>(a) None.<br>(b) None.  | 1 Ton.                   |
| 4.      | 50252. Jet Spur Geared Chain Block.<br>(a) None.<br>(b) None.   | ½ Ton.                   |
| 5.      | 50247. Jet Spur Geared Chain Block.<br>(a) None.<br>(b) None.   | ½ Ton.                   |
|         | Latest date for completion of next thorough inspection:<br>Date of last previous through inspection:  | 23-3-2012.<br>30-3-2010. |

Inspections in accordance with LIFTING OPERATIONS AND LIFTING EQUIPMENT REGULATIONS 1998.

I certify that on 23<sup>rd</sup> March 2011. I carried out a thorough examination of all accessible parts of the lifting machine and above is an accurate report of such examination.

Signature..........Robert C.C Healey.  
Qualification Consultant Engineer  
Lifting Machinery Consultants & Surveyors

# LIFTING MACHINERY CONSULTANTS & SURVEYORS

PINE RIDGE, ERCALL HEATH, NR. NEWPORT, SHROPSHIRE. TEL: 01952 550539

## Report Of Examination Of Lifting Machine


|                    |                        |
|--------------------|------------------------|
| Contract No. 1022. | Report No. 1022/34/3A. |
|--------------------|------------------------|

|  |
|--|
| Contact Name Prism Lighting,<br>Address Unit 5A, Hampton Heath Industrial Estate, Hampton Heath, Malpas, Cheshire. |
|--|

| Item No | Distinguishing number or mark and description<br>(a) Defects effecting safe working and repairs required immediately or within a specified time.<br>(b) Other defects, their remedies and observations. | Safe Working Load.       |
|---------|---|--------------------------|
| 1.      | 071227525. Yale Spur Geared Chain Block.<br>(a) None.<br>(b) None.  | ½ Ton.                   |
| 2.      | 071227540. Yale Spur Geared Chain Block.<br>(a) None.<br>(b) None.  | ½ Ton.                   |
| 3.      | 071227541. Yale Spur Geared Chain Block.<br>(a) None.<br>(b) None.  | ½ Ton.                   |
| 4.      | 071227570. Yale Spur Geared Chain Block.<br>(a) None.<br>(b) None.  | ½ Ton.                   |
| 5.      | 071227596. Yale Spur Geared Chain Block.<br>(a) None.<br>(b) None.  | ½ Ton.                   |
|         | Latest date for completion of next thorough inspection:<br>Date of last previous through inspection:  | 23-3-2012.<br>30-3-2010. |

Inspections in accordance with LIFTING OPERATIONS AND LIFTING EQUIPMENT REGULATIONS 1998.

I certify that on 23<sup>rd</sup> March 2011. I carried out a thorough examination of all accessible parts of the lifting machine and above is an accurate report of such examination.

Signature..........Robert C.C Healey.  
Qualification Consultant Engineer  
Lifting Machinery Consultants & Surveyors

# LIFTING MACHINERY CONSULTANTS & SURVEYORS

PINE RIDGE, ERCALL HEATH, NR. NEWPORT, SHROPSHIRE. TEL: 01952 550539

## Report Of Examination Of Lifting Machine


|                    |                        |
|--------------------|------------------------|
| Contract No. 1022. | Report No. 1022/34/3B. |
|--------------------|------------------------|

|  |
|--|
| Contact Name Prism Lighting,<br>Address Unit 5A, Hampton Heath Industrial Estate, Hampton Heath, Malpas, Cheshire. |
|--|

| Item No | Distinguishing number or mark and description<br>(a) Defects effecting safe working and repairs required immediately or within a specified time.<br>(b) Other defects, their remedies and observations. | Safe Working Load.       |
|---------|---|--------------------------|
| 1.      | 071227606. Yale Spur Geared Chain Block.<br>(a) None.<br>(b) None.  | ½ Ton.                   |
| 2.      | 071227607. Yale Spur Geared Chain Block.<br>(a) None.<br>(b) None.  | ½ Ton.                   |
| 3.      | 071227674. Yale Spur Geared Chain Block.<br>(a) None.<br>(b) None.  | ½ Ton.                   |
| 4.      | 071227675. Yale Spur Geared Chain Block.<br>(a) None.<br>(b) None.  | ½ Ton.                   |
| 5.      | 071227695. Yale Spur Geared Chain Block.<br>(a) None.<br>(b) None.  | ½ Ton.                   |
|         | Latest date for completion of next thorough inspection:<br>Date of last previous through inspection:  | 23-3-2012.<br>30-3-2010. |

Inspections in accordance with LIFTING OPERATIONS AND LIFTING EQUIPMENT REGULATIONS 1998.

I certify that on 23<sup>rd</sup> March 2011. I carried out a thorough examination of all accessible parts of the lifting machine and above is an accurate report of such examination.

Signature..........Robert C.C Healey.  
Qualification Consultant Engineer  
Lifting Machinery Consultants & Surveyors

# LIFTING MACHINERY CONSULTANTS & SURVEYORS

PINE RIDGE, ERCALL HEATH, NR. NEWPORT, SHROPSHIRE. TEL: 01952 550539

## Report Of Examination Of Lifting Machine


|                    |                        |
|--------------------|------------------------|
| Contract No. 1022. | Report No. 1022/34/3C. |
|--------------------|------------------------|

|  |
|--|
| Contact Name Prism Lighting,<br>Address Unit 5A, Hampton Heath Industrial Estate, Hampton Heath, Malpas, Cheshire. |
|--|

| Item No | Distinguishing number or mark and description<br>(a) Defects effecting safe working and repairs required immediately or within a specified time.<br>(b) Other defects, their remedies and observations. | Safe Working Load.       |
|---------|---|--------------------------|
| 1.      | 071227805. Yale Spur Geared Chain Block.<br><br>(a) None.<br>(b) None.  | ½ Ton.                   |
| 2.      | 071227741. Yale Spur Geared Chain Block.<br><br>(a) None.<br>(b) None.  | ½ Ton.                   |
|         |   |                          |
|         |   |                          |
|         |   |                          |
|         |   |                          |
|         | Latest date for completion of next thorough inspection:<br>Date of last previous through inspection:  | 23-3-2012.<br>30-3-2010. |

Inspections in accordance with LIFTING OPERATIONS AND LIFTING EQUIPMENT REGULATIONS 1998.

I certify that on 23<sup>rd</sup> March 2011. I carried out a thorough examination of all accessible parts of the lifting machine and above is an accurate report of such examination.

Signature..........Robert C.C Healey.  
Qualification Consultant Engineer  
Lifting Machinery Consultants & Surveyors

# LIFTING MACHINERY CONSULTANTS & SURVEYORS

PINE RIDGE, ERCALL HEATH, NR. NEWPORT, SHROPSHIRE. TEL: 01952 550539

## Report Of Examination Of Lifting Machine


|                    |                       |
|--------------------|-----------------------|
| Contract No. 1022. | Report No. 1022/34/4. |
|--------------------|-----------------------|

|  |
|--|
| Contact Name Prism Lighting,<br>Address Unit 5A, Hampton Heath Industrial Estate, Hampton Heath, Malpas, Cheshire. |
|--|

| Item No | Distinguishing number or mark and description<br>(a) Defects effecting safe working and repairs required immediately or within a specified time.<br>(b) Other defects, their remedies and observations. | Safe Working Load.                   |
|---------|---|--------------------------------------|
| 1.      | 938 A. Jet Rope Hoist.<br><br>(a) None.<br>(b) None.  | 8000 KG Lifting.<br>1200 KG Pulling. |
| 2.      | 07930. Jet Rope Hoist.<br><br>(a) None.<br>(b) None.  | 8000 KG Lifting.<br>1200 KG Pulling. |
|         |   |                                      |
|         |   |                                      |
|         |   |                                      |
|         | Latest date for completion of next thorough inspection:<br>Date of last previous through inspection:  | 23-3-2012.<br>30-3-2010.             |

Inspections in accordance with LIFTING OPERATIONS AND LIFTING EQUIPMENT REGULATIONS 1998.

I certify that on 23<sup>rd</sup> March 2011. I carried out a thorough examination of all accessible parts of the lifting machine and above is an accurate report of such examination.

Signature..........Robert C.C Healey.  
Qualification Consultant Engineer  
Lifting Machinery Consultants & Surveyors

# LIFTING MACHINERY CONSULTANTS & SURVEYORS

PINE RIDGE, ERCALL HEATH, NR. NEWPORT, SHROPSHIRE. TEL: 01952 550539

## Report Of Examination Of Lifting Machine

|                    |                       |
|--------------------|-----------------------|
| Contract No. 1022. | Report No. 1022/34/5. |
|--------------------|-----------------------|

|  |
|--|
| Contact Name Prism Lighting,<br>Address Unit 5A, Hampton Heath Industrial Estate, Hampton Heath, Malpas, Cheshire. |
|--|

| Item No | Distinguishing number or mark and description<br>(a) Defects effecting safe working and repairs required immediately or within a specified time.<br>(b) Other defects, their remedies and observations. | Safe Working Load.       |
|---------|---|--------------------------|
| 1.      | B.17206. Morris Ungearred Four Wheel Trolley.<br><br>(a) None.<br>(b) None.   | 10 Cwts.                 |
| 2.      | R 3. 7" x 4" U/Beam Overhead Runway x 4.8 Meters.<br><br>(a) None.<br>(b) None.   | 10 Cwts.                 |
|         |   |                          |
|         |   |                          |
|         |   |                          |
|         | Latest date for completion of next thorough inspection:<br>Date of last previous through inspection:  | 23-3-2012.<br>29-3-2010. |

Inspections in accordance with LIFTING OPERATIONS AND LIFTING EQUIPMENT REGULATIONS 1998.

I certify that on 23<sup>rd</sup> March 2011. I carried out a thorough examination of all accessible parts of the lifting machine and above is an accurate report of such examination.

Signature..........Robert C.C Healey.  
Qualification Consultant Engineer  
Lifting Machinery Consultants & Surveyors

# LIFTING MACHINERY CONSULTANTS & SURVEYORS

PINE RIDGE, ERCALL HEATH, NR. NEWPORT, SHROPSHIRE. TEL: 01952 550539

## Report Of Examination Of Lifting Machine


|                    |                       |
|--------------------|-----------------------|
| Contract No. 1022. | Report No. 1022/34/6. |
|--------------------|-----------------------|

|  |
|--|
| Contact Name Prism Lighting,<br>Address Unit 5A, Hampton Heath Industrial Estate, Hampton Heath, Malpas, Cheshire. |
|--|

| Item No | Distinguishing number or mark and description<br>(a) Defects effecting safe working and repairs required immediately or within a specified time.<br>(b) Other defects, their remedies and observations. | Safe Working Load.       |
|---------|---|--------------------------|
| 1.      | 000808903. Spanset Horizontal Safety Line.<br>None.   |                          |
| 2.      | 000816007. Spanset Horizontal Safety Line.<br>None.   |                          |
|         |   |                          |
|         |   |                          |
|         |   |                          |
|         | Latest date for completion of next thorough inspection:<br>Date of last previous through inspection:  | 23-3-2012.<br>29-3-2010. |

Inspections in accordance with LIFTING OPERATIONS AND LIFTING EQUIPMENT REGULATIONS 1998.

I certify that on 23<sup>rd</sup> March 2011. I carried out a thorough examination of all accessible parts of the lifting machine and above is an accurate report of such examination.

Signature..........Robert C.C Healey.  
Qualification Consultant Engineer  
Lifting Machinery Consultants & Surveyors

# LIFTING MACHINERY CONSULTANTS & SURVEYORS

PINE RIDGE, ERCALL HEATH, NR. NEWPORT, SHROPSHIRE. TEL: 01952 550539

## Report Of Examination Of Lifting Machine


|                    |                       |
|--------------------|-----------------------|
| Contract No. 1022. | Report No. 1022/34/7. |
|--------------------|-----------------------|

|  |
|--|
| Contact Name Prism Lighting,<br>Address Unit 5A, Hampton Heath Industrial Estate, Hampton Heath, Malpas, Cheshire. |
|--|

| Item No | Distinguishing number or mark and description<br>(a) Defects effecting safe working and repairs required immediately or within a specified time.<br>(b) Other defects, their remedies and observations. | Safe Working Load.       |
|---------|---|--------------------------|
| 1.      | 95-163408. Wahlefeld Fall Arrester Unit.<br><br>(a) None.<br>(b) None.  |                          |
| 2.      | 95-163410. Wahlefeld Fall Arrester Unit.<br><br>(a) None.<br>(b) None.  |                          |
| 3.      | 68919. Protecta Fall Arrester Unit.<br><br>(a) None.<br>(b) None.   |                          |
| 4.      | 68920. Protecta Fall Arrester Unit.<br><br>(a) None.<br>(b) None.   |                          |
|         |   |                          |
|         | Latest date for completion of next thorough inspection:<br>Date of last previous through inspection:  | 23-3-2012.<br>29-3-2010. |

Inspections in accordance with LIFTING OPERATIONS AND LIFTING EQUIPMENT REGULATIONS 1998.

I certify that on 23<sup>rd</sup> March 2011. I carried out a thorough examination of all accessible parts of the lifting machine and above is an accurate report of such examination.

Signature..........Robert C.C Healey.  
Qualification Consultant Engineer  
Lifting Machinery Consultants & Surveyors

# LIFTING MACHINERY CONSULTANTS & SURVEYORS

PINE RIDGE, ERCALL HEATH, NR. NEWPORT, SHROPSHIRE. TEL:01952 550539

## Report of Examination Of Chains, Ropes & Lifting Tackle

| Contract No. 1022.  |   | Report No. 1022/35/8.             |
|---|---|-----------------------------------|
| Name of Occupier. Prism Lighting,   |   |                                   |
| Address. Unit 5A, Hampton Heath Industrial Estate, Hampton Heath, Malpas, Cheshire. |   |                                   |
| Item No.  | Distinguishing number or mark and description<br>Defects found and steps to remedy them. General remarks. | Safe Working Load<br>CODE YELLOW. |
| 1.  | PR 104-48452/8. Master Link.<br>None.   | 4 Ton.                            |
| 2.  | UR.11597. Master Link.<br>None.   | 4 Ton.                            |
| 3.  | PR 106-48452/10. Master Link.<br>None.  | 4 Ton.                            |
| 4.  | 8462. Master Link.<br>Not located at time of inspection.  | 5.3 Tons.                         |
| 5.  | 19. Master Link.<br>None.   | 2000 KG.                          |
| 6.  | A.1012. Master Link.<br>None.   | 8 Ton.                            |
| 7.  | No. Unknown. Master Link.<br>5 links Not located at time of inspection.                                   | 5.3 Tons.                         |
| 8.  | 8331. Master Link.<br>Not located at time of inspection.  | 4.2 Ton.                          |
| 9.  | No. Unk. Master Link.<br>Not located at time of inspection.   | 2000 KG.                          |
| 10.   | CG 106/T. Master Link.<br>4 links examined in order mark number and safe working loads.                   |                                   |
|   |   |                                   |
|   |   |                                   |
|   |   |                                   |
|   | Latest date for completion of next thorough Inspection:   | 21-3-2012.                        |
|   | Date of last previous thorough Inspection:  | 21-3-2011.                        |

I certify that on 21<sup>st</sup> September 2011. I examined the above plant and the above is an accurate report of that examination.

INSPECTIONS IN ACCORDANCE WITH /LIFTING OPERATIONS AND  
LIFTING EQUIPMENT REGULATIONS 1998

Inspecting Engineer.....

Signature..........Robert C.C Healey.

Qualification Consultant Engineer

Lifting Machinery Consultants & Surveyors



# LIFTING MACHINERY CONSULTANTS & SURVEYORS

PINE RIDGE, ERCALL HEATH, NR. NEWPORT, SHROPSHIRE. TEL:01952 550539

## Report of Examination Of Chains, Ropes & Lifting Tackle

| Contract No.      | 1022.   | Report No.                        | 1022/35/10. |
|-------------------|---|-----------------------------------|-------------|
| Name of Occupier. | Prism Lighting,   |                                   |             |
| Address.          | Unit 5A, Hampton Heath Industrial Estate, Hampton Heath, Malpas, Cheshire.                                |                                   |             |
| Item No.          | Distinguishing number or mark and description<br>Defects found and steps to remedy them. General remarks. | Safe Working Load<br>CODE YELLOW. |             |
| 1.                | 49225 A. Stac Chain.<br>None.   | 5.4 Ton.                          |             |
| 2.                | 49225 B. Stac Chain.<br>None.   | 5.4 Ton.                          |             |
| 3.                | 1119921. Stac Chain.<br>None.   | 5.4 Ton.                          |             |
| 4.                | 1119922. Stac Chain.<br>None.   | 5.4 Ton.                          |             |
| 5.                | 1119923. Stac Chain.<br>None.   | 5.4 Ton.                          |             |
| 6.                | 1119924. Stac Chain.<br>None.   | 5.4 Ton.                          |             |
| 7.                | 1119925. Stac Chain.<br>None.   | 5.4 Ton.                          |             |
| 8.                | 1119926. Stac Chain.<br>None.   | 5.4 Ton.                          |             |
| 9.                | ACC5076. Stac Chain.<br>None.   | 5.4 Ton.                          |             |
| 10.               | ACC5077. Stac Chain.<br>None.   | 5.4 Ton.                          |             |
| 11.               | ACC5074. Stac Chain.<br>None.   | 5.4 Ton.                          |             |
| 12.               | ACC5075. Stac Chain.<br>None.   | 5.2 Ton.                          |             |
|                   |   |                                   |             |
|                   | Latest date for completion of next thorough Inspection:   | 21-3-2012.                        |             |
|                   | Date of last previous thorough Inspection:  | 21-3-2011.                        |             |

I certify that on 21<sup>st</sup> September 2011. I examined the above plant and the above is an accurate report of that examination.

INSPECTIONS IN ACCORDANCE WITH /LIFTING OPERATIONS AND  
LIFTING EQUIPMENT REGULATIONS 1998

Inspecting Engineer.....

Signature..........Robert C.C Healey.

Qualification Consultant Engineer

Lifting Machinery Consultants & Surveyors

# LIFTING MACHINERY CONSULTANTS & SURVEYORS


PINE RIDGE, ERCALL HEATH, NR. NEWPORT, SHROPSHIRE. TEL:01952 550539

## Report of Examination Of Chains, Ropes & Lifting Tackle

| Contract No. 1022.  |  | Report No. 1022/35/11.            |
|---|--|-----------------------------------|
| Name of Occupier. Prism Lighting,   |  |                                   |
| Address. Unit 5A, Hampton Heath Industrial Estate, Hampton Heath, Malpas, Cheshire. |  |                                   |
| Item No.  | Distinguishing number or mark and description<br>Defects found and steps to remedy them. General remarks.  | Safe Working Load<br>CODE YELLOW. |
|   | The following numbered 11 mm x 5' Wire Rope Slings were examined and found to be in good order. Hook and Eye.<br>PR 1, 2, 4, 7, 9, 311, 313.   | 1000 KG.                          |
|   | The following numbered 11 mm x 5' Wire Rope Slings were examined and found to be in good order. Hook and Ring.<br>PR 121, 122, 123, 124, 125, 126, 127, 128, 129, 130, 131, 132, 133, 134, 135, 137, 262, 263, 264.<br>34889/1, 34889/2, 34889/10. | 1.5 Tonne.                        |
|   |  |                                   |
|   |  |                                   |
|   |  |                                   |
|   |  |                                   |
|   |  |                                   |
|   |  |                                   |
|   |  |                                   |
|   |  |                                   |
|   |  |                                   |
|   |  |                                   |
|   | Latest date for completion of next thorough Inspection:<br>Date of last previous thorough Inspection:  | 21-3-2012.<br>21-3-2011.          |

I certify that on 21<sup>st</sup> September 2011. I examined the above plant and the above is an accurate report of that examination.

INSPECTIONS IN ACCORDANCE WITH /LIFTING OPERATIONS AND  
LIFTING EQUIPMENT REGULATIONS 1998

Inspecting Engineer.....  
Signature..........Robert C.C Healey.

Qualification Consultant Engineer  
Lifting Machinery Consultants & Surveyors

# LIFTING MACHINERY CONSULTANTS & SURVEYORS


PINE RIDGE, ERCALL HEATH, NR. NEWPORT, SHROPSHIRE. TEL:01952 550539

## Report of Examination Of Chains, Ropes & Lifting Tackle

| Contract No. 1022.  |  | Report No. 1022/35/11A.           |
|---|--|-----------------------------------|
| Name of Occupier. Prism Lighting,   |  |                                   |
| Address. Unit 5A, Hampton Heath Industrial Estate, Hampton Heath, Malpas, Cheshire. |  |                                   |
| Item No.  | Distinguishing number or mark and description<br>Defects found and steps to remedy them. General remarks.    | Safe Working Load<br>CODE YELLOW. |
|   | The following numbered 11 mm x 5' Wire Rope Slings were examined and found to be in good order. Eye and Eye. | 1 Tonne.                          |
|   | PR 102, 103, 105, 106, 110, 112, 113, 115, 116, 117, 118, 120, 301.  |                                   |
|   | The following numbered 11 mm x 5' Wire Rope Slings were examined and found to be in good order. Eye and Eye. | 1.5 Tonne.                        |
|   | 50683/ 25, 26, 28, 29, 30, 31, 32, 33, 34, 36, 37, 38, 39, 40.<br>53486/ 2, 4, 6.                            |                                   |
|   |  |                                   |
|   |  |                                   |
|   |  |                                   |
|   |  |                                   |
|   |  |                                   |
|   |  |                                   |
|   |  |                                   |
|   |  |                                   |
|   | Latest date for completion of next thorough Inspection:  | 21-3-2012.                        |
|   | Date of last previous thorough Inspection:   | 21-3-2011.                        |

I certify that on 21<sup>st</sup> September 2011. I examined the above plant and the above is an accurate report of that examination.

INSPECTIONS IN ACCORDANCE WITH /LIFTING OPERATIONS AND  
LIFTING EQUIPMENT REGULATIONS 1998

Inspecting Engineer.....  
Signature..........Robert C.C Healey.  
Qualification Consultant Engineer

Lifting Machinery Consultants & Surveyors

# LIFTING MACHINERY CONSULTANTS & SURVEYORS

PINE RIDGE, ERCALL HEATH, NR. NEWPORT, SHROPSHIRE. TEL:01952 550539

## Report of Examination Of Chains, Ropes & Lifting Tackle

| Contract No. 1022.  |   | Report No. 1022/35/11B.           |
|---|---|-----------------------------------|
| Name of Occupier. Prism Lighting,   |   |                                   |
| Address. Unit 5A, Hampton Heath Industrial Estate, Hampton Heath, Malpas, Cheshire. |   |                                   |
| Item No.  | Distinguishing number or mark and description<br>Defects found and steps to remedy them. General remarks. | Safe Working Load<br>CODE YELLOW. |
|   |   |                                   |
|   | The following numbered 11 mm x 5' Wire Rope Slings were examined and found to be in good order. Soft Eye. | 1.4 Tonne.                        |
|   | 4864, 4685.   |                                   |
|   | <b>NOT LOCATED AT TIME OF INSPECTION.</b> 4865.   |                                   |
|   | The following numbered 11 mm x 5' Wire Rope Slings were examined and found to be in good order. Soft Eye. | 1 Tonne.                          |
|   | PR 166. CE2523/1. CE2522/2.   |                                   |
|   |   |                                   |
|   |   |                                   |
|   |   |                                   |
|   |   |                                   |
|   |   |                                   |
|   |   |                                   |
|   |   |                                   |
|   |   |                                   |
|   | Latest date for completion of next thorough Inspection:   | 21-3-2012.                        |
|   | Date of last previous thorough Inspection:  | 21-3-2011.                        |

I certify that on 21<sup>st</sup> September 2011. I examined the above plant and the above is an accurate report of that examination.

INSPECTIONS IN ACCORDANCE WITH /LIFTING OPERATIONS AND  
LIFTING EQUIPMENT REGULATIONS 1998

Inspecting Engineer.....

Signature.....*Robert C.C Healey*.....Robert C.C Healey.

Qualification Consultant Engineer

Lifting Machinery Consultants & Surveyors

# LIFTING MACHINERY CONSULTANTS & SURVEYORS

PINE RIDGE, ERCALL HEATH, NR. NEWPORT, SHROPSHIRE. TEL:01952 550539

## Report of Examination Of Chains, Ropes & Lifting Tackle

| Contract No. 1022.  |   | Report No. 1022/35/12.            |
|---|---|-----------------------------------|
| Name of Occupier. Prism Lighting,   |   |                                   |
| Address. Unit 5A, Hampton Heath Industrial Estate, Hampton Heath, Malpas, Cheshire. |   |                                   |
| Item No.  | Distinguishing number or mark and description<br>Defects found and steps to remedy them. General remarks.                         | Safe Working Load<br>CODE YELLOW. |
|   | The following numbered 11 mm x 5' Wire Rope Slings were examined and found to be in good order. Eye and Eye.                      | 2 Ton.                            |
|   | BSR 253326/ 35, 36, 37, 38, 39, 40, 41, 42, 43, 44, 45, 46, 47, 48, 49, 50, 51, 52.   |                                   |
|   |   |                                   |
|   | The following numbered 11 mm x 2 M Wire Rope Slings were examined and found to be in good order. Eye and Eye.                     | 2 Tonne.                          |
|   | 37015/ 2, 3, 5, 6, 7, 9, 10.  |                                   |
|   |   |                                   |
|   | The following numbered 11 mm x 5' Wire Rope Slings were examined and found to be in good order. Eye and Eye.                      | <b>Clear Plastic.</b><br>1000 KG. |
|   | BSRP. 51, 52, 54, 55, 56, 57, 58, 61, 62, 64, 65, 67, 69, 70, 72, 73, 74, 75, 76, 77, 78, 79, 81, 83, 84, 85, 86, 87, 88, 89, 90. |                                   |
|   | <b>NOT LOCATED AT TIME OF INSPECTION.</b> BSRP 53, 59, 60, 63, 66, 68, 71, 80, 82.  |                                   |
|   | The following numbered 11 mm x 2.4 M Wire Rope Slings were examined and found to be in good order. Eye and Eye.                   | 1000 KG.                          |
|   | BSR 258764/ 15, 16, 17, 18, 19, 20, 21, 22, 23, 24, 25, 26, 27, 28, 29, 30, 31, 32, 33, 34.                                       |                                   |
|   | The following numbered 11 mm x 2'-10" Wire Rope Slings were examined and found to be in good order. Hook and Eye.                 | 1000 KG.                          |
|   | BSR 258764/ 1, 2, 3, 5, 7, 9, 10, 11, 12, 14.<br>PR 252. <b>NOT LOCATED AT TIME OF INSPECTION.</b> 4, 6, 8, 13.                   |                                   |
|   | Latest date for completion of next thorough Inspection:   | 21-3-2012.                        |
|   | Date of last previous thorough Inspection:  | 21-3-2011.                        |

I certify that on 21<sup>st</sup> September 2011. I examined the above plant and the above is an accurate report of that examination.

INSPECTIONS IN ACCORDANCE WITH /LIFTING OPERATIONS AND  
LIFTING EQUIPMENT REGULATIONS 1998

Inspecting Engineer.....

Signature..........Robert C.C Healey.

Qualification Consultant Engineer

Lifting Machinery Consultants & Surveyors

# LIFTING MACHINERY CONSULTANTS & SURVEYORS

PINE RIDGE, ERCALL HEATH, NR. NEWPORT, SHROPSHIRE. TEL:01952 550539

## Report of Examination Of Chains, Ropes & Lifting Tackle

| Contract No. 1022.  |   | Report No. 1022/35/13.            |
|---|---|-----------------------------------|
| Name of Occupier. Prism Lighting,   |   |                                   |
| Address. Unit 5A, Hampton Heath Industrial Estate, Hampton Heath, Malpas, Cheshire. |   |                                   |
| Item No.  | Distinguishing number or mark and description<br>Defects found and steps to remedy them. General remarks.                   | Safe Working Load<br>CODE YELLOW. |
|   | The following numbered 11 mm x 1.5 M Wire Rope Slings were examined and found to be in good order. Eye and Eye. Black Poly. | 1.0 Tonne.                        |
|   | BSR30/ 1, 2, 6, 7, 9, 10, 14, 15, 16, 17, 20, 23, 24, 27, 28, 29, 30, 32, 34, 35, 36, 38, 39.                               |                                   |
|   | <b>NOT LOCATED AT TIME OF INSPECTION.</b> 3, 4, 5, 8, 11, 12, 13, 19, 21, 22, 25, 26, 31, 33, 37.                           |                                   |
|   |   |                                   |
|   | The following numbered 11 mm x 0.5 M Wire Rope Slings were examined and found to be in good order. Hook and Eye.            | 1.5 Tons.                         |
|   | EWR 50683/ 64, 65, 66, 67, 68.<br><b>NOT LOCATED AT TIME OF INSPECTION.</b> 63.   |                                   |
|   |   |                                   |
|   | The following numbered 11 mm x 2'-6" Wire Rope Slings were examined and found to be in good order. Hook and Eye.            | 1.5 Tonnes.                       |
|   | 50683/ 6, 57, 58, 59, 61, 62.<br><b>NOT LOCATED AT TIME OF INSPECTION.</b> BSR 258764/8.                                    |                                   |
|   |   |                                   |
|   |   |                                   |
|   |   |                                   |
|   |   |                                   |
|   | Latest date for completion of next thorough Inspection:   | 21-3-2012.                        |
|   | Date of last previous thorough Inspection:  | 21-3-2011.                        |

I certify that on 21<sup>st</sup> September 2011. I examined the above plant and the above is an accurate report of that examination.

INSPECTIONS IN ACCORDANCE WITH /LIFTING OPERATIONS AND  
LIFTING EQUIPMENT REGULATIONS 1998

Inspecting Engineer.....  
Signature..........Robert C.C Healey.  
Qualification Consultant Engineer

Lifting Machinery Consultants & Surveyors

# LIFTING MACHINERY CONSULTANTS & SURVEYORS

PINE RIDGE, ERCALL HEATH, NR. NEWPORT, SHROPSHIRE. TEL:01952 550539

## Report of Examination Of Chains, Ropes & Lifting Tackle

| Contract No. 1022.  |  | Report No. 1022/35/14.            |
|---|--|-----------------------------------|
| Name of Occupier. Prism Lighting,   |  |                                   |
| Address. Unit 5A, Hampton Heath Industrial Estate, Hampton Heath, Malpas, Cheshire. |  |                                   |
| Item No.  | Distinguishing number or mark and description<br>Defects found and steps to remedy them. General remarks.      | Safe Working Load<br>CODE YELLOW. |
|   | The following numbered 11 mm x 10" Wire Rope Slings were examined and found to be in good order. Eye and Eye.  | 1000 KG.                          |
|   | PR 351, 353, 355, 357, 361, 362, 363, 366, 367, 368, 373.  |                                   |
|   | <b>NOT LOCATED AT TIME OF INSPECTION.</b> 354, 356, 358, 359, 360, 365, 369, 370.                              |                                   |
|   | The following numbered 11 mm x 10' Wire Rope Slings were examined and found to be in good order. Hook and Eye. | 1 Ton.                            |
|   | PR201H.  |                                   |
|   |  |                                   |
|   | The following numbered 11 mm x 10' Wire Rope Slings were examined and found to be in good order. Eye and Eye.  | 2 Ton.                            |
|   | PR 701, 702, 703, 704, 706, 707.<br>40191/10, 40191/16.  |                                   |
|   | 253326/ 17, 18, 19, 20, 21, 22, 23, 24, 25, 26, 27, 28, 29, 30, 31, 32, 33, 34.                                |                                   |
|   |  |                                   |
|   | The following numbered 11 mm x 10' Wire Rope Slings were examined and found to be in good order. Eye and Eye.  | 1.4 Tonnes.                       |
|   | PR 371, 374, 375, 377, 379, 381, 383, 389, 392, 394.   |                                   |
|   | <b>NOT LOCATED.</b><br>382, 384, 385, 391, 395.  |                                   |
|   | Latest date for completion of next thorough Inspection:<br>Date of last previous thorough Inspection:          | 21-3-2012.<br>21-3-2011.          |

I certify that on 21<sup>st</sup> September 2011. I examined the above plant and the above is an accurate report of that examination.

INSPECTIONS IN ACCORDANCE WITH /LIFTING OPERATIONS AND  
LIFTING EQUIPMENT REGULATIONS 1998

Inspecting Engineer.....  
Signature.....*Robert C.C Healey*.....Robert C.C Healey.  
Qualification Consultant Engineer

Lifting Machinery Consultants & Surveyors

# LIFTING MACHINERY CONSULTANTS & SURVEYORS


PINE RIDGE, ERCALL HEATH, NR. NEWPORT, SHROPSHIRE. TEL:01952 550539

## Report of Examination Of Chains, Ropes & Lifting Tackle

| Contract No. 1022.  |   | Report No. 1022/35/15.            |
|---|---|-----------------------------------|
| Name of Occupier. Prism Lighting,   |   |                                   |
| Address. Unit 5A, Hampton Heath Industrial Estate, Hampton Heath, Malpas, Cheshire. |   |                                   |
| Item No.  | Distinguishing number or mark and description<br>Defects found and steps to remedy them. General remarks.     | Safe Working Load<br>CODE YELLOW. |
|   | The following numbered 11 mm x 20' Wire Rope Slings were examined and found to be in good order. Eye and Eye. | 1000 KG.                          |
|   | PR 402, 403, 407, 410, 413, 414, 415, 418.  |                                   |
|   | <b>NOT LOCATED AT TIME OF INSPECTION.</b> 417, 420.   |                                   |
|   | The following numbered 11 mm x 20' Wire Rope Slings were examined and found to be in good order. Eye and Eye. | 1.5 Tonnes.                       |
|   | 26213/8.  |                                   |
|   | <b>NOT LOCATED AT TIME OF INSPECTION.</b><br>26213/1, 26213/2, 26213/5.                                       |                                   |
|   |   |                                   |
|   | The following numbered 11 mm x 20' Wire Rope Slings were examined and found to be in good order. Eye and Eye. | 2 Ton.                            |
|   | 40191/ 3, 4, 5, 6, 8.<br>253326/ 7, 8, 9, 10, 11, 12, 13, 14, 15, 16.   |                                   |
|   |   |                                   |
|   |   |                                   |
|   |   |                                   |
|   |   |                                   |
|   | Latest date for completion of next thorough Inspection:   | 21-3-2012.                        |
|   | Date of last previous thorough Inspection:  | 21-3-2011.                        |

I certify that on 21<sup>st</sup> September 2011. I examined the above plant and the above is an accurate report of that examination.

INSPECTIONS IN ACCORDANCE WITH /LIFTING OPERATIONS AND  
LIFTING EQUIPMENT REGULATIONS 1998

Inspecting Engineer.....  
Signature..........Robert C.C Healey.  
Qualification Consultant Engineer

Lifting Machinery Consultants & Surveyors

# LIFTING MACHINERY CONSULTANTS & SURVEYORS

PINE RIDGE, ERCALL HEATH, NR. NEWPORT, SHROPSHIRE. TEL:01952 550539

## Report of Examination Of Chains, Ropes & Lifting Tackle

| Contract No. 1022.  |   | Report No. 1022/35/16.            |
|---|---|-----------------------------------|
| Name of Occupier. Prism Lighting.   |   |                                   |
| Address. Unit 5A, Hampton Heath Industrial Estate, Hampton Heath, Malpas, Cheshire. |   |                                   |
| Item No.  | Distinguishing number or mark and description<br>Defects found and steps to remedy them. General remarks.     | Safe Working Load<br>CODE YELLOW. |
|   | The following numbered 11 mm x 30' Wire Rope Slings were examined and found to be in good order. Eye and Eye. | 1.5 Tons.                         |
|   | EWR 50683/ 1, 2, 3, 4, 5, 6, 7, 9, 10, 11, 12, 14, 15, 16, 17, 18, 19, 21, 23.                                |                                   |
|   | <b>NOT LOCATED AT TIME OF INSPECTION.</b><br>EWR 50683/ 8, 13, 20, 22.  |                                   |
|   |   |                                   |
|   | The following numbered 11 mm x 30' Wire Rope Slings were examined and found to be in good order. Eye and Eye. | 1000 KG.                          |
|   | PR 606, 607, 608, 610, 611, 612.  |                                   |
|   | <b>NOT LOCATED AT TIME OF INSPECTION.</b><br>609.   |                                   |
|   | The following numbered 11 mm x 30' Wire Rope Slings were examined and found to be in good order. Eye and Eye. | 2 Ton.                            |
|   | BSR 253326/ 1, 2, 3, 4, 5, 6.   |                                   |
|   |   |                                   |
|   |   |                                   |
|   |   |                                   |
|   |   |                                   |
|   | Latest date for completion of next thorough Inspection:   | 21-3-2012.                        |
|   | Date of last previous thorough Inspection:  | 21-3-2011.                        |

I certify that on 21<sup>st</sup> September 2011. I examined the above plant and the above is an accurate report of that examination.

INSPECTIONS IN ACCORDANCE WITH /LIFTING OPERATIONS AND  
LIFTING EQUIPMENT REGULATIONS 1998

Inspecting Engineer.....  
Signature..........Robert C.C Healey.  
Qualification Consultant Engineer

Lifting Machinery Consultants & Surveyors



# LIFTING MACHINERY CONSULTANTS & SURVEYORS

PINE RIDGE, ERCALL HEATH, NR. NEWPORT, SHROPSHIRE. TEL:01952 550539

## Report of Examination Of Chains, Ropes & Lifting Tackle

| Contract No. 1022.  |   | Report No. 1022/35/17A.           |
|---|---|-----------------------------------|
| Name of Occupier. Prism Lighting,   |   |                                   |
| Address. Unit 5A, Hampton Heath Industrial Estate, Hampton Heath, Malpas, Cheshire. |   |                                   |
| Item No.  | Distinguishing number or mark and description<br>Defects found and steps to remedy them. General remarks.     | Safe Working Load<br>CODE YELLOW. |
|   | The following numbered 11 mm x 3 M Wire Rope Slings were examined and found to be in good order. Eye and Eye. | 1 Tonne.                          |
|   | BSRP 41, 44.  |                                   |
|   | NOT LOCATED AT TIME OF INSPECTION.<br>42, 43.   |                                   |
|   | The following numbered 11 mm x 6 M Wire Rope Slings were examined and found to be in good order. Eye and Eye. | 1 Tonne.                          |
|   | BSRP 45, 46, 47, 48, 49, 50.  |                                   |
|   |   |                                   |
| 1.  | JH 49576 AA9. Single Leg Clutch Chain.<br>None.   | 1.5 Tonne.                        |
| 2.  | JH 49576 AA14. Single Leg Clutch Chain.<br>None.  | 1.5 Tonne.                        |
|   |   |                                   |
|   |   |                                   |
|   |   |                                   |
|   | Latest date for completion of next thorough Inspection:   | 21-3-2012.                        |
|   | Date of last previous thorough Inspection:  | 21-3-2011.                        |

I certify that on 21<sup>st</sup> September 2011. I examined the above plant and the above is an accurate report of that examination.

INSPECTIONS IN ACCORDANCE WITH /LIFTING OPERATIONS AND  
LIFTING EQUIPMENT REGULATIONS 1998

Inspecting Engineer.....

Signature..........Robert C.C Healey.

Qualification Consultant Engineer

Lifting Machinery Consultants & Surveyors

# LIFTING MACHINERY CONSULTANTS & SURVEYORS


PINE RIDGE, ERCALL HEATH, NR. NEWPORT, SHROPSHIRE. TEL:01952 550539

## Report of Examination Of Chains, Ropes & Lifting Tackle

| Contract No. 1022.  |   | Report No. 1022/35/18.            |
|---|---|-----------------------------------|
| Name of Occupier. Prism Lighting,   |   |                                   |
| Address. Unit 5A, Hampton Heath Industrial Estate, Hampton Heath, Malpas, Cheshire. |   |                                   |
| Item No.  | Distinguishing number or mark and description<br>Defects found and steps to remedy them. General remarks. | Safe Working Load<br>CODE YELLOW. |
|   | The following numbered Spanset Slings x 1M Circ were examined and found to be in good order.              | 2 Ton.                            |
|   | 000351026.  |                                   |
|   |   |                                   |
|   |   |                                   |
|   | 2074422, 2074455,<br>2074471, 2063203, 2074397.   | 2000 KG.                          |
|   | <b>NOT LOCATED AT TIME OF INSPECTION.</b><br>2074396, 2074423, 2074432, 2074396.                          |                                   |
|   | 07/ 325350, 325351, 325352, 325354, 325355, 325358,<br>325359, 325361.                                    |                                   |
|   | 290959, 290962, 290971, 290973, 290984, 290992,<br>291782, 2090966.                                       |                                   |
|   | <b>NOT LOCATED AT TIME OF INSPECTION.</b><br>2074286, 291789, 325356, 325360, 290993.                     |                                   |
|   | 07/ 290968.   |                                   |
|   |   |                                   |
|   |   |                                   |
|   | Latest date for completion of next thorough Inspection:<br>Date of last previous thorough Inspection:     | 21-3-2012.<br>21-3-2011.          |

I certify that on 21<sup>st</sup> September 2011. I examined the above plant and the above is an accurate report of that examination.

INSPECTIONS IN ACCORDANCE WITH /LIFTING OPERATIONS AND  
LIFTING EQUIPMENT REGULATIONS 1998

Inspecting Engineer.....  
Signature........Robert C.C Healey.

Qualification Consultant Engineer  
Lifting Machinery Consultants & Surveyors

# LIFTING MACHINERY CONSULTANTS & SURVEYORS


PINE RIDGE, ERCALL HEATH, NR. NEWPORT, SHROPSHIRE. TEL:01952 550539

## Report of Examination Of Chains, Ropes & Lifting Tackle

| Contract No. 1022.  |  | Report No. 1022/35/19.            |
|---|--|-----------------------------------|
| Name of Occupier. Prism Lighting,   |  |                                   |
| Address. Unit 5A, Hampton Heath Industrial Estate, Hampton Heath, Malpas, Cheshire. |  |                                   |
| Item No.  | Distinguishing number or mark and description<br>Defects found and steps to remedy them. General remarks.                    | Safe Working Load<br>CODE YELLOW. |
|   | The following numbered Spanset Slings x 2 M Circ were examined and found to be in good order.                                | 2000 KG.                          |
|   | PR 607. (NOT LOCATED AT TIME OF INSPECTION PR 606)<br>716220.  |                                   |
|   | NOT LOCATED AT TIME OF INSPECTION 000351032, 000351034,<br>000351036, 000351039, 000351041, 000493194, 000493182, 000493202. |                                   |
|   | 2036431, 2036475, 2036484, 2036525, 2036560, 2036536,<br>NOT LOCATED 2036435, 2036485, 2036558, 2036562, 2036566, 2036568.   |                                   |
|   | 31838, 31840, 31843, 31846.<br>NOT LOCATED 31820, 31821, 31826, 31829, 31830, 31844, 31849, 31852.                           |                                   |
|   | 63419, 63422, 63425, 63436. NOT LOCATED 63420, 63421, 63423, 63424,<br>63427, 63428, 63430, 63431.                           |                                   |
|   | 325362, 325373. NOT LOCATED 1427992, 31350, 325363, 325364, 325365,<br>325366, 325367, 325369, 325370, 325372, 325376.       |                                   |
|   |  |                                   |
|   | The following numbered Spanset Slings x 2 M Circ were examined and found to be in good order.                                | 2000 KG.                          |
|   | E209, E240, E241, E468, E864, E873, E874, E875, E876,<br>E884, E893.   |                                   |
|   | NOT LOCATED AT TIME OF INSPECTION E869, E877, E881, E885.  |                                   |
|   |  |                                   |
|   | Latest date for completion of next thorough Inspection:<br>Date of last previous thorough Inspection:                        | 21-3-2012.<br>21-3-2011.          |

I certify that on 21<sup>st</sup> September 2011. I examined the above plant and the above is an accurate report of that examination.

INSPECTIONS IN ACCORDANCE WITH /LIFTING OPERATIONS AND  
LIFTING EQUIPMENT REGULATIONS 1998

Inspecting Engineer.....  
Signature...  ..... Robert C.C Healey.  
Qualification Consultant Engineer  
Lifting Machinery Consultants & Surveyors

# LIFTING MACHINERY CONSULTANTS & SURVEYORS

PINE RIDGE, ERCALL HEATH, NR. NEWPORT, SHROPSHIRE. TEL:01952 550539

## Report of Examination Of Chains, Ropes & Lifting Tackle

| Contract No. 1022.  |  | Report No. 1022/35/20.            |
|---|--|-----------------------------------|
| Name of Occupier. Prism Lighting,   |  |                                   |
| Address. Unit 5A, Hampton Heath Industrial Estate, Hampton Heath, Malpas, Cheshire. |  |                                   |
| Item No.  | Distinguishing number or mark and description<br>Defects found and steps to remedy them. General remarks.          | Safe Working Load<br>CODE YELLOW. |
|   | The following numbered Spanset Slings x 3 M Circ were examined and found to be in good order.                      | 1000 KG.                          |
|   | 43/9.  |                                   |
|   | The following numbered Spanset Slings x 3 M Circ were examined and found to be in good order.                      | 2000 KG.                          |
|   | 000351044, 000351045, 000351049, 000351050, 000351051.<br>(NOT LOCATED AT TIME OF INSPECTION 000351046, 000351048) |                                   |
|   | 325375, 325376, 325384, 325385, 580432.  |                                   |
|   | (NOT LOCATED 353370, 325374, 325377, 325378, 325379, 325380, 325381, 325382, 325383)                               |                                   |
|   |  |                                   |
|   |  |                                   |
|   |  |                                   |
|   |  |                                   |
|   |  |                                   |
|   | Latest date for completion of next thorough Inspection:  | 21-3-2012.                        |
|   | Date of last previous thorough Inspection:   | 21-3-2011.                        |

I certify that on 21<sup>st</sup> September 2011. I examined the above plant and the above is an accurate report of that examination.

INSPECTIONS IN ACCORDANCE WITH /LIFTING OPERATIONS AND  
LIFTING EQUIPMENT REGULATIONS 1998

Inspecting Engineer.....

Signature...  ..... Robert C.C Healey.

Qualification Consultant Engineer

Lifting Machinery Consultants & Surveyors

# LIFTING MACHINERY CONSULTANTS & SURVEYORS

PINE RIDGE, ERCALL HEATH, NR. NEWPORT, SHROPSHIRE. TEL:01952 550539

## Report of Examination Of Chains, Ropes & Lifting Tackle

| Contract No. 1022.  |  | Report No. 1022/35/21.            |
|---|--|-----------------------------------|
| Name of Occupier. Prism Lighting,   |  |                                   |
| Address. Unit 5A, Hampton Heath Industrial Estate, Hampton Heath, Malpas, Cheshire. |  |                                   |
| Item No.  | Distinguishing number or mark and description<br>Defects found and steps to remedy them. General remarks.          | Safe Working Load<br>CODE YELLOW. |
|   | The following numbered Spanset Slings x 4 M Circ were examined and found to be in good order.                      | 2000 KG.                          |
|   | PR 1402, 1408, 1409, 1418, 1420, 1427, 1428, 1431.   |                                   |
|   | 35603/3, 35603/4.<br>(NOT LOCATED 35603/2, 35603/7, 35603/10.)   |                                   |
|   | 000351056, 000351057, 000351060.<br>000351062, 000351063, 000351066, 000351067, 000351068,                         |                                   |
|   | 000351075, 000351076, 000351077,<br>000351078, 000351080, 000351082,   |                                   |
|   | 000351089, 000351090, 000351091,<br>R.15496, 184832.   |                                   |
|   | (NOT LOCATED 000351087, 000351052, 000351059, 000351069, 000351072,<br>000351081, 000351083, 000351086, 000380595) |                                   |
|   | The following numbered Spanset Slings x 4 M Circ were examined and found to be in good order.                      | 1000 KG.                          |
|   | PR 1206, 1209, 1210.   |                                   |
|   | 55/15/6, 55/15/7.<br>776. 52891.   |                                   |
|   | Latest date for completion of next thorough Inspection:<br>Date of last previous thorough Inspection:              | 21-3-2012.<br>21-3-2011.          |

I certify that on 21<sup>st</sup> September 2011. I examined the above plant and the above is an accurate report of that examination.

INSPECTIONS IN ACCORDANCE WITH /LIFTING OPERATIONS AND  
LIFTING EQUIPMENT REGULATIONS 1998

Inspecting Engineer.....  
Signature. .....Robert C.C Healey.  
Qualification Consultant Engineer

Lifting Machinery Consultants & Surveyors

# LIFTING MACHINERY CONSULTANTS & SURVEYORS

PINE RIDGE, ERCALL HEATH, NR. NEWPORT, SHROPSHIRE. TEL:01952 550539

## Report of Examination Of Chains, Ropes & Lifting Tackle

| Contract No. 1022.  |   | Report No. 1022/35/22.            |
|---|---|-----------------------------------|
| Name of Occupier. Prism Lighting,   |   |                                   |
| Address. Unit 5A, Hampton Heath Industrial Estate, Hampton Heath, Malpas, Cheshire. |   |                                   |
| Item No.  | Distinguishing number or mark and description<br>Defects found and steps to remedy them. General remarks.                     | Safe Working Load<br>CODE YELLOW. |
|   | The following numbered Spanset Slings x 6 M Circ were examined and found to be in good order.                                 | 1000 KG.                          |
|   | PR 1601.  |                                   |
|   | The following numbered Spanset Slings x 6 M Circ were examined and found to be in good order.                                 | 2000 KG.                          |
|   | PR 1803, 1804, 1805, 1806, 1808 worn but serviceable, 1815, 1817, 1818, 1819, 1820, 1821, 1823, 1825, 1827, 1829.             |                                   |
|   | 000351094, 000351098, 000351099, 000351100, 000351101, 000560837, 00056821. (NOT LOCATED 000351060, 000351092,)               |                                   |
|   | The following numbered Spanset Slings x 8 M Circ were examined and found to be in good order.                                 | 2000 KG.                          |
|   | PR 2201, 2202.  |                                   |
|   | 1881408, 1881409, 1881410, 1881411, 1881413, 1881414, 1881415, 1881416, 1881417, 1881418, 1988810, 1988811, 1988812, 1988815. | 2 Ton.                            |
|   |   |                                   |
|   |   |                                   |
|   | Latest date for completion of next thorough Inspection:   | 21-3-2012.                        |
|   | Date of last previous thorough Inspection:  | 21-3-2011.                        |

I certify that on 21<sup>st</sup> September 2011. I examined the above plant and the above is an accurate report of that examination.

INSPECTIONS IN ACCORDANCE WITH /LIFTING OPERATIONS AND  
LIFTING EQUIPMENT REGULATIONS 1998

Inspecting Engineer.....

Signature..........Robert C.C Healey.

Qualification Consultant Engineer

Lifting Machinery Consultants & Surveyors

# LIFTING MACHINERY CONSULTANTS & SURVEYORS

PINE RIDGE, ERCALL HEATH, NR. NEWPORT, SHROPSHIRE. TEL:01952 550539

## Report of Examination Of Climbing Ropes

| Contract No. 1022.  |   | Report No. 1022/35/23.            |
|---|---|-----------------------------------|
| Name of Occupier. Prism Lighting,   |   |                                   |
| Address. Unit 5A, Hampton Heath Industrial Estate, Hampton Heath, Malpas, Cheshire. |   |                                   |
| Item No.  | Distinguishing number or mark and description<br>Defects found and steps to remedy them. General remarks. | Safe Working Load<br>CODE YELLOW. |
|   | The following numbered Climbing Ropes x 15 M were all examined and found to be in good order.             |                                   |
|   | SL 2, 3, 4, 5, 6, 7, 8, 9, 10, 11, 12, 13.  |                                   |
|   |   |                                   |
|   | The following numbered Climbing Ropes x 20 M were all examined and found to be in good order.             |                                   |
|   | HR2001, HR2002.   |                                   |
|   |   |                                   |
|   | The following numbered Climbing Ropes x 30 M were all examined and found to be in good order.             |                                   |
|   | HR3001.   |                                   |
|   |   |                                   |
|   | The following numbered Climbing Ropes x 40 M were all examined and found to be in good order.             |                                   |
|   | HR4002.<br>NOT LOCATED AT TIME OF INSPECTION HR4001.  |                                   |
|   | Girder Clamp.<br>01535, 01585 were NOT EXAMINED AS NOT LOCATED.   |                                   |
|   | Latest date for completion of next thorough Inspection:   | 21-3-2012.                        |
|   | Date of last previous thorough Inspection:  | 21-3-2011.                        |

I certify that on 21<sup>st</sup> September 2011. I examined the above plant and the above is an accurate report of that examination.

INSPECTIONS IN ACCORDANCE WITH /LIFTING OPERATIONS AND  
LIFTING EQUIPMENT REGULATIONS 1998

Inspecting Engineer .....

Signature..........Robert C.C Healey.

Qualification Consultant Engineer

Lifting Machinery Consultants & Surveyors