

Report of Thorough Examination of Lifting Equipment

This report complies with the requirements of the Lifting Operations and Lifting Equipment Regulations 1998

Date of Thorough Examination: 06 Feb 2012	Date of Report: 07 Feb 2012	Report Number: R019456-1
--	------------------------------------	---------------------------------

Name and address of employer for whom the thorough examination was made: PRISM LIGHTING LIMITED 5A HAMPTON INDUSTRIAL ESTATE MALPAS CHESHIRE SY14 8JQ	Address of premises at which the examination was made: PRISM LIGHTING LIMITED 5A HAMPTON INDUSTRIAL ESTATE MALPAS CHESHIRE SY14 8JQ	Our Job No: T 019524
--	--	-------------------------

Description and identification of the equipment: Plant Number L1 Serial Number L3344NG Equipment Desc. ELECTRIC CHAIN HOIST MODEL: CM LODESTAR SPEED 4MPM HEIGHT OF LIFT: 20M Location	Safe working load(s): 1000 KG	Date of manufacture if known:	Date of last thorough examination: 04/02/2011
---	--------------------------------------	-------------------------------	--

Is this an examination carried out upon the supply of the Equipment? <input checked="" type="checkbox"/> NO	Was the examination carried out: Within an interval of 6 months? <input checked="" type="checkbox"/> NO
Is this the first examination after installation or after assembly at a new site or location? <input checked="" type="checkbox"/> NO	Within an interval of 12 months? <input checked="" type="checkbox"/> YES
If the answer to the above question is YES, has the equipment been installed correctly? <input type="checkbox"/> N/A	In accordance with an examination scheme? <input checked="" type="checkbox"/> NO
	After the occurrence of exceptional circumstances? <input checked="" type="checkbox"/> NO


Type of Examination \ Test Carried Out: Load Test	Examination Result \ Equipment Status: No Defects Found
--	--

(A) Defects In Need of Attention To Prevent Immediate Failure & Details of Action Required to rectify Defects: None	(B) Defects to be Kept Under Observation, Date When Defects Must Be Rectified By and Parts Required: None
--	--

Are the above defects as stated in section (A) of Immediate Danger to Persons? Note: Any Defect which is not yet, but could become a danger to persons as stated in section (B) above must be rectified by the date specified above in section (B).	<input type="checkbox"/> NO
--	-----------------------------

Particulars of Any Tests Carried Out as Part of the Examination: CALIBRATED TEST WEIGHTS 1250 KG	Additional Comments Made As Part of This Examination:
---	---


EQUIPMENT SAFE TO OPERATE? <input checked="" type="checkbox"/> Yes	Latest Date for Next Thorough Examination: 05 Feb 2013
--	---

Examination Carried Out By Mercian Lifting Gear (UK) Limited Netherwood Road Rotherwas Industrial Estate Hereford HR2 6JU	Name of the person making this report: Name GRAHAM THOMAS Position Service Engineer	Name of the person authenticating this report: Name TONY BAILEY Date 07 Feb 2012 Signature 
--	---	---

Report of Thorough Examination of Lifting Equipment

This report complies with the requirements of the Lifting Operations and Lifting Equipment Regulations 1998


Date of Thorough Examination: 06 Feb 2012		Date of Report: 07 Feb 2012		Report Number: R019457-2	
Name and address of employer for whom the thorough examination was made: PRISM LIGHTING LIMITED 5A HAMPTON INDUSTRIAL ESTATE MALPAS CHESHIRE SY14 8JQ		Address of premises at which the examination was made: PRISM LIGHTING LIMITED 5A HAMPTON INDUSTRIAL ESTATE MALPAS CHESHIRE SY14 8JQ		Our Job No: T 019524	
Description and identification of the equipment: Plant Number L2 Serial Number L3347NG Equipment Desc. ELECTRIC CHAIN HOIST MODEL: CM LOADSTAR SPEED: 4 MPM HEIGHT OF LIFT: 20M Location		Safe working load(s): 1000 KGS	Date of manufacture if known:	Date of last thorough examination: 04/02/2011	
Is this an examination carried out upon the supply of the Equipment?	<input checked="" type="checkbox"/> NO	Was the examination carried out:		<input checked="" type="checkbox"/> NO	
Is this the first examination after installation or after assembly at a new site or location?	<input checked="" type="checkbox"/> NO	Within an interval of 6 months?		<input checked="" type="checkbox"/> YES	
If the answer to the above question is YES, has the equipment been installed correctly?	N/A	Within an interval of 12 months?		<input checked="" type="checkbox"/> NO	
		In accordance with an examination scheme?		<input checked="" type="checkbox"/> NO	
		After the occurrence of exceptional circumstances?		<input checked="" type="checkbox"/> NO	
Type of Examination \ Test Carried Out: Load Test		Examination Result \ Equipment Status: No Defects Found			
(A) Defects In Need of Attention To Prevent Immediate Failure & Details of Action Required to rectify Defects: None		(B) Defects to be Kept Under Observation, Date When Defects Must Be Rectified By and Parts Required: None			
Are the above defects as stated in section (A) of Immediate Danger to Persons? Note: Any Defect which is not yet, but could become a danger to persons as stated in section (B) above must be rectified by the date specified above in section (B).					NO
Particulars of Any Tests Carried Out as Part of the Examination: CALIBRATED TEST WEIGHTS 1250 KG		Additional Comments Made As Part of This Examination:			
EQUIPMENT SAFE TO OPERATE? <input checked="" type="checkbox"/> Yes		Latest Date for Next Thorough Examination: 05 Feb 2013			

Examination Carried Out By Mercian Lifting Gear (UK) Limited Netherwood Road Rotherwas Industrial Estate Hereford HR2 6JU	Name of the person making this report:		Name of the person authenticating this report:	
	Name	GRAHAM THOMAS	Name	TONY BAILEY
	Position	Service Engineer	Date	07 Feb 2012
			Signature	

Report of Thorough Examination of Lifting Equipment

This report complies with the requirements of the Lifting Operations and Lifting Equipment Regulations 1998

Date of Thorough Examination: 06 Feb 2012		Date of Report: 07 Feb 2012		Report Number: R019458-3	
Name and address of employer for whom the thorough examination was made: PRISM LIGHTING LIMITED 5A HAMPTON INDUSTRIAL ESTATE MALPAS CHESHIRE SY14 8JQ		Address of premises at which the examination was made: PRISM LIGHTING LIMITED 5A HAMPTON INDUSTRIAL ESTATE MALPAS CHESHIRE SY14 8JQ		Our Job No: T 019524	
Description and identification of the equipment: Plant Number L3 Serial Number L3357NG Equipment Desc. ELECTRIC CHAIN HOIST MODEL: CM LOADSTAR SPEED: 4 MPM HEIGHT OF LIFT: 32M Location		Safe working load(s): 1000 KGS	Date of manufacture if known:	Date of last thorough examination: 01/02/2011	
Is this an examination carried out upon the supply of the Equipment? <input checked="" type="checkbox"/> NO		Was the examination carried out: Within an interval of 6 months? <input checked="" type="checkbox"/> NO		Within an interval of 12 months? <input checked="" type="checkbox"/> YES	
Is this the first examination after installation or after assembly at a new site or location? <input checked="" type="checkbox"/> NO		In accordance with an examination scheme? <input checked="" type="checkbox"/> NO		After the occurrence of exceptional circumstances? <input checked="" type="checkbox"/> NO	
If the answer to the above question is YES, has the equipment been installed correctly? <input type="checkbox"/> N/A					
Type of Examination \ Test Carried Out: Load Test		Examination Result \ Equipment Status: No Defects Found			
(A) Defects In Need of Attention To Prevent Immediate Failure & Details of Action Required to rectify Defects: None		(B) Defects to be Kept Under Observation, Date When Defects Must Be Rectified By and Parts Required: None			
Are the above defects as stated in section (A) of Immediate Danger to Persons? Note: Any Defect which is not yet, but could become a danger to persons as stated in section (B) above must be rectified by the date specified above in section (B).		<input type="checkbox"/> NO			
Particulars of Any Tests Carried Out as Part of the Examination: CALIBRATED TEST WEIGHTS 1250 KG		Additional Comments Made As Part of This Examination:			
EQUIPMENT SAFE TO OPERATE? <input checked="" type="checkbox"/> Yes		Latest Date for Next Thorough Examination: 05 Feb 2013			

Examination Carried Out By Mercian Lifting Gear (UK) Limited Netherwood Road Rotherwas Industrial Estate Hereford HR2 6JU	Name of the person making this report: Name GRAHAM THOMAS Position Service Engineer	Name of the person authenticating this report: Name TONY BAILEY Date 07 Feb 2012 Signature 
--	---	---

Report of Thorough Examination of Lifting Equipment

This report complies with the requirements of the Lifting Operations and Lifting Equipment Regulations 1998

Date of Thorough Examination: 05 Oct 2011	Date of Report: 06 Oct 2011	Report Number: R018375-1
--	------------------------------------	---------------------------------

Name and address of employer for whom the thorough examination was made: PRISM LIGHTING LIMITED 5A HAMPTON INDUSTRIAL ESTATE MALPAS CHESHIRE SY14 8JQ	Address of premises at which the examination was made: PRISM LIGHTING LIMITED 5A HAMPTON INDUSTRIAL ESTATE MALPAS CHESHIRE SY14 8JQ	Our Job No: T 018669
--	--	-------------------------

Description and identification of the equipment: Plant Number L4 Serial Number L3358NG Equipment Desc. 1 NO. ELECTRIC CHAIN HOIST MAKE : CM LODESTAR HEIGHT OF LIFT : 22M SERIAL NO. L3358NG PLANT NO. L4 Location PRISM	Safe working load(s): 1000 KGS	Date of manufacture if known:	Date of last thorough examination: 13/10/2010
--	-----------------------------------	-------------------------------	--

Is this an examination carried out upon the supply of the Equipment? <input checked="" type="checkbox"/> NO	Was the examination carried out: Within an interval of 6 months? <input checked="" type="checkbox"/> NO
Is this the first examination after installation or after assembly at a new site or location? <input checked="" type="checkbox"/> NO	Within an interval of 12 months? <input checked="" type="checkbox"/> YES
If the answer to the above question is YES, has the equipment been installed correctly? <input type="checkbox"/> N/A	In accordance with an examination scheme? <input checked="" type="checkbox"/> NO
	After the occurrence of exceptional circumstances? <input checked="" type="checkbox"/> NO


Type of Examination \ Test Carried Out: Load Test	Examination Result \ Equipment Status: No Defects Found
--	--

(A) Defects In Need of Attention To Prevent Immediate Failure & Details of Action Required to rectify Defects: None	(B) Defects to be Kept Under Observation, Date When Defects Must Be Rectified By and Parts Required: None
--	--

Are the above defects as stated in section (A) of Immediate Danger to Persons?
Note: Any Defect which is not yet, but could become a danger to persons as stated in section (B) above must be rectified by the date specified above in section (B).
 NO

Particulars of Any Tests Carried Out as Part of the Examination: CALIBRATED TEST WEIGHTS 1250 KG	Additional Comments Made As Part of This Examination:
---	---


EQUIPMENT SAFE TO OPERATE? <input checked="" type="checkbox"/> Yes	Latest Date for Next Thorough Examination: 04 Oct 2012
---	---

Examination Carried Out By Mercian Lifting Gear (UK) Limited Netherwood Road Rotherwas Industrial Estate Hereford HR2 6JU	Name of the person making this report: Name ALLAN PERKINS Position SERVICE ENGINEER	Name of the person authenticating this report: Name TONY BAILEY Date 06 Oct 2011 Signature 
--	---	---

Report of Thorough Examination of Lifting Equipment

This report complies with the requirements of the Lifting Operations and Lifting Equipment Regulations 1998

Date of Thorough Examination: 06 May 2011		Date of Report: 06 May 2011		Report Number: 016474-3	
Name and address of employer for whom the thorough examination was made: PRISM LIGHTING LIMITED 5A HAMPTON INDUSTRIAL ESTATE MALPAS CHESHIRE SY14 8JQ			Address of premises at which the examination was made: PRISM LIGHTING LIMITED 5A HAMPTON INDUSTRIAL ESTATE MALPAS CHESHIRE SY14 8JQ		
Description and identification of the equipment: Plant Number L5 Serial Number L-1785NT Equipment Desc. ELECTRIC CHAIN HOIST MAKE : CM LODESTAR HEIGHT OF LIFT : 18M SERIAL NO. L-1785NT Location PLANT NO. L5		Safe working load(s): 1000 KG	Date of manufacture if known:	Date of last thorough examination: 08/04/2009	
Is this an examination carried out upon the supply of the Equipment? <input checked="" type="checkbox"/> NO		Was the examination carried out: Within an interval of 6 months? <input checked="" type="checkbox"/> NO		<input checked="" type="checkbox"/> YES	
Is this the first examination after installation or after assembly at a new site or location? <input checked="" type="checkbox"/> NO		Within an interval of 12 months? <input checked="" type="checkbox"/> YES		<input checked="" type="checkbox"/> NO	
If the answer to the above question is YES, has the equipment been installed correctly? <input type="checkbox"/> N/A		In accordance with an examination scheme? <input checked="" type="checkbox"/> NO		<input checked="" type="checkbox"/> NO	
Type of Examination \ Test Carried Out: Proof Load Test		Examination Result \ Equipment Status: No Defects Found			
(A) Defects In Need of Attention To Prevent Immediate Failure & Details of Action Required to rectify Defects: None		(B) Defects to be Kept Under Observation, Date When Defects Must Be Rectified By and Parts Required: None			
Are the above defects as stated in section (A) of Immediate Danger to Persons? Note: Any Defect which is not yet, but could become a danger to persons as stated in section (B) above must be rectified by the date specified above in section (B).					<input checked="" type="checkbox"/> NO
Particulars of Any Tests Carried Out as Part of the Examination: PROOF LOAD TEST TO 1250 KG			Additional Comments Made As Part of This Examination:		
EQUIPMENT SAFE TO OPERATE? <input checked="" type="checkbox"/> Yes			Latest Date for Next Thorough Examination: 07 May 2012		

Examination Carried Out By Mercian Lifting Gear (UK) Limited Netherwood Road Rotherwas Industrial Estate Hereford HR2 6JU	Name of the person making this report: Name GRAHAM THOMAS Position Service Engineer	Name of the person authenticating this report: Name TONY BAILEY Date 06 May 2011 Signature 
--	---	---

Report of Thorough Examination of Lifting Equipment

This report complies with the requirements of the Lifting Operations and Lifting Equipment Regulations 1998

Date of Thorough Examination: 09 Feb 2012	Date of Report: 09 Feb 2012	Report Number: R019472-8
--	------------------------------------	---------------------------------

Name and address of employer for whom the thorough examination was made: PRISM LIGHTING LIMITED 5A HAMPTON INDUSTRIAL ESTATE MALPAS CHESHIRE SY14 8JQ	Address of premises at which the examination was made: PRISM LIGHTING LIMITED 5A HAMPTON INDUSTRIAL ESTATE MALPAS CHESHIRE SY14 8JQ	Our Job No: T 019524
--	--	-------------------------

Description and identification of the equipment: Plant Number L6 Serial Number LI810NT Equipment Desc. ELECTRIC CHAIN HOIST MODEL: CM LODESTAR SPEED: 4MPM HEIGHT OF LIFT: 20M Location	Safe working load(s): 1000 KG	Date of manufacture if known:	Date of last thorough examination: 01/02/2011
--	--------------------------------------	-------------------------------	--

Is this an examination carried out upon the supply of the Equipment? <input checked="" type="checkbox"/> NO	Was the examination carried out: Within an interval of 6 months? <input checked="" type="checkbox"/> NO
Is this the first examination after installation or after assembly at a new site or location? <input checked="" type="checkbox"/> NO	Within an interval of 12 months? <input checked="" type="checkbox"/> YES
If the answer to the above question is YES, has the equipment been installed correctly? <input type="checkbox"/> N/A	In accordance with an examination scheme? <input checked="" type="checkbox"/> NO
	After the occurrence of exceptional circumstances? <input checked="" type="checkbox"/> NO

Type of Examination \ Test Carried Out: Load Test	Examination Result \ Equipment Status: No Defects Found
--	---


(A) Defects In Need of Attention To Prevent Immediate Failure & Details of Action Required to rectify Defects: None	(B) Defects to be Kept Under Observation, Date When Defects Must Be Rectified By and Parts Required: None
--	--

Are the above defects as stated in section (A) of Immediate Danger to Persons?
Note: Any Defect which is not yet, but could become a danger to persons as stated in section (B) above must be rectified by the date specified above in section (B).

NO

Particulars of Any Tests Carried Out as Part of the Examination: CALIBRATED TEST WEIGHTS 1250 KG	Additional Comments Made As Part of This Examination:
---	---


EQUIPMENT SAFE TO OPERATE? <input checked="" type="checkbox"/> Yes	Latest Date for Next Thorough Examination: 08 Feb 2013
---	---

Examination Carried Out By Mercian Lifting Gear (UK) Limited Netherwood Road Rotherwas Industrial Estate Hereford HR2 6JU	Name of the person making this report: Name GRAHAM THOMAS Position Service Engineer	Name of the person authenticating this report: Name TONY BAILEY Date 09 Feb 2012 Signature 
--	---	---

Report of Thorough Examination of Lifting Equipment

This report complies with the requirements of the Lifting Operations and Lifting Equipment Regulations 1998

Date of Thorough Examination: 06 May 2011	Date of Report: 06 May 2011	Report Number: 016475-4
Name and address of employer for whom the thorough examination was made: PRISM LIGHTING LIMITED 5A HAMPTON INDUSTRIAL ESTATE MALPAS CHESHIRE SY14 8JQ		Address of premises at which the examination was made: PRISM LIGHTING LIMITED 5A HAMPTON INDUSTRIAL ESTATE MALPAS CHESHIRE SY14 8JQ
Description and identification of the equipment: Plant Number L7 Serial Number L-0824NV Equipment Desc. ELECTRIC CHAIN HOIST MODEL: CM LODESTAR SPEED: 4 MPM HEIGHT OF LIFT: 21M Location	Safe working load(s): 1000 KG	Date of manufacture if known: Date of last thorough examination: 21/04/2010
Is this an examination carried out upon the supply of the Equipment? <input checked="" type="checkbox"/> NO	Was the examination carried out: Within an interval of 6 months? <input checked="" type="checkbox"/> NO	<input checked="" type="checkbox"/> YES
Is this the first examination after installation or after assembly at a new site or location? <input checked="" type="checkbox"/> NO	Within an interval of 12 months? <input checked="" type="checkbox"/> YES	<input checked="" type="checkbox"/> NO
If the answer to the above question is YES, has the equipment been installed correctly? <input type="checkbox"/> N/A	In accordance with an examination scheme? <input checked="" type="checkbox"/> NO	<input checked="" type="checkbox"/> NO
After the occurrence of exceptional circumstances? <input checked="" type="checkbox"/> NO		
Type of Examination/Test Carried Out: Proof Load Test	Examination Result \ Equipment Status: No Defects Found	
(A) Defects In Need of Attention To Prevent Immediate Failure & Details of Action Required to rectify Defects: None	(B) Defects to be Kept Under Observation, Date When Defects Must Be Rectified By and Parts Required: None	
Are the above defects as stated in section (A) of Immediate Danger to Persons? Note: Any Defect which is not yet, but could become a danger to persons as stated in section (B) above must be rectified by the date specified above in section (B).		<input checked="" type="checkbox"/> NO
Particulars of Any Tests Carried Out as Part of the Examination: PROOF LOAD TEST TO 1250 KG	Additional Comments Made As Part of This Examination:	
EQUIPMENT SAFE TO OPERATE? <input checked="" type="checkbox"/> Yes	Latest Date for Next Thorough Examination: 07 May 2012	

Examination Carried Out By Mercian Lifting Gear (UK) Limited Netherwood Road Rotherwas Industrial Estate Hereford HR2 6JU	Name of the person making this report: Name GRAHAM THOMAS Position Service Engineer	Name of the person authenticating this report: Name TONY BAILEY Date 06 May 2011 Signature 
--	---	---

Report of Thorough Examination of Lifting Equipment

This report complies with the requirements of the Lifting Operations and Lifting Equipment Regulations 1998

Date of Thorough Examination: 05 Oct 2011	Date of Report: 06 Oct 2011	Report Number: R018377-3
--	------------------------------------	---------------------------------

Name and address of employer for whom the thorough examination was made: PRISM LIGHTING LIMITED 5A HAMPTON INDUSTRIAL ESTATE MALPAS CHESHIRE SY14 8JQ	Address of premises at which the examination was made: PRISM LIGHTING LIMITED 5A HAMPTON INDUSTRIAL ESTATE MALPAS CHESHIRE SY14 8JQ	Our Job No: T 018669
--	--	-------------------------

Description and identification of the equipment: Plant Number LB Serial Number L0810NV Equipment Desc. 1 NO. ELECTRIC CHAIN HOIST MAKE : CM LODESTAR HEIGHT OF LIFT : 21M SERIAL NO. L0810NV PLANT NO. LB Location PRISM	Safe working load(s): 1000 KGS	Date of manufacture if known:	Date of last thorough examination: 13/10/2010
--	---------------------------------------	-------------------------------	--

Is this an examination carried out upon the supply of the Equipment? <input checked="" type="checkbox"/> NO	Was the examination carried out: Within an interval of 6 months? <input checked="" type="checkbox"/> NO
Is this the first examination after installation or after assembly at a new site or location? <input checked="" type="checkbox"/> NO	Within an interval of 12 months? <input checked="" type="checkbox"/> YES
If the answer to the above question is YES, has the equipment been installed correctly? <input type="checkbox"/> N/A	In accordance with an examination scheme? <input checked="" type="checkbox"/> NO
	After the occurrence of exceptional circumstances? <input checked="" type="checkbox"/> NO


Type of Examination \ Test Carried Out: Load Test	Examination Result \ Equipment Status: No Defects Found
--	--

(A) Defects In Need of Attention To Prevent Immediate Failure & Details of Action Required to rectify Defects: None	(B) Defects to be Kept Under Observation, Date When Defects Must Be Rectified By and Parts Required: None
--	--

Are the above defects as stated in section (A) of Immediate Danger to Persons? Note: Any Defect which is not yet, but could become a danger to persons as stated in section (B) above must be rectified by the date specified above in section (B).	<input type="checkbox"/> NO
--	-----------------------------

Particulars of Any Tests Carried Out as Part of the Examination: CALIBRATED TEST WEIGHTS 1250 KG	Additional Comments Made As Part of This Examination:
---	---


EQUIPMENT SAFE TO OPERATE? <input checked="" type="checkbox"/> Yes	Latest Date for Next Thorough Examination: 04 Oct 2012
---	---

Examination Carried Out By Mercian Lifting Gear (UK) Limited Netherwood Road Rotherwas Industrial Estate Hereford HR2 6JU	Name of the person making this report: Name ALLAN PERKINS Position SERVICE ENGINEER	Name of the person authenticating this report: Name TONY BAILEY Date 06 Oct 2011 Signature 
--	---	---

Report of Thorough Examination of Lifting Equipment

This report complies with the requirements of the Lifting Operations and Lifting Equipment Regulations 1998


Date of Thorough Examination: 05 Oct 2011		Date of Report: 06 Oct 2011		Report Number: R018376-2	
Name and address of employer for whom the thorough examination was made: PRISM LIGHTING LIMITED 5A HAMPTON INDUSTRIAL ESTATE MALPAS CHESHIRE SY14 8JQ		Address of premises at which the examination was made: PRISM LIGHTING LIMITED 5A HAMPTON INDUSTRIAL ESTATE MALPAS CHESHIRE SY14 8JQ		Our Job No: T 018669	
Description and identification of the equipment: Plant Number L9 Serial Number L-0327 PJ Equipment Desc. 1 NO. ELECTRIC CHAIN HOIST MAKE : CM LODESTAR HEIGHT OF LIFT : 20M SERIAL NO. L-0327 PJ PLANT NO. L9 Location PRISM		Safe working load(s): 1000 KGS	Date of manufacture if known:	Date of last thorough examination: 13/10/2010	
Is this an examination carried out upon the supply of the Equipment? <input checked="" type="checkbox"/> NO		Was the examination carried out: Within an interval of 6 months? <input checked="" type="checkbox"/> NO		<input checked="" type="checkbox"/> YES	
Is this the first examination after installation or after assembly at a new site or location? <input checked="" type="checkbox"/> NO		Within an interval of 12 months? <input checked="" type="checkbox"/> NO		<input checked="" type="checkbox"/> YES	
If the answer to the above question is YES, has the equipment been installed correctly? <input type="checkbox"/> N/A		In accordance with an examination scheme? <input checked="" type="checkbox"/> NO		<input checked="" type="checkbox"/> YES	
After the occurrence of exceptional circumstances? <input checked="" type="checkbox"/> NO					
Type of Examination \ Test Carried Out: Load Test		Examination Result \ Equipment Status: No Defects Found			
(A) Defects in Need of Attention To Prevent Immediate Failure & Details of Action Required to rectify Defects: None		(B) Defects to be Kept Under Observation, Date When Defects Must Be Rectified By and Parts Required: None			
Are the above defects as stated in section (A) of Immediate Danger to Persons? Note: Any Defect which is not yet, but could become a danger to persons as stated in section (B) above must be rectified by the date specified above in section (B).		<input type="checkbox"/> NO			
Particulars of Any Tests Carried Out as Part of the Examination: CALIBRATED TEST WEIGHTS 1250 KG		Additional Comments Made As Part of This Examination:			
EQUIPMENT SAFE TO OPERATE? <input checked="" type="checkbox"/> Yes		Latest Date for Next Thorough Examination: 04 Oct 2012			

Examination Carried Out By Mercian Lifting Gear (UK) Limited Netherwood Road Rotherwas Industrial Estate Hereford HR2 6JU	Name of the person making this report: Name ALLAN PERKINS Position SERVICE ENGINEER	Name of the person authenticating this report: Name TONY BAILEY Date 06 Oct 2011 Signature 
--	---	---

Report of Thorough Examination of Lifting Equipment

This report complies with the requirements of the Lifting Operations and Lifting Equipment Regulations 1998


Date of Thorough Examination: 05 Oct 2011		Date of Report: 06 Oct 2011		Report Number: R018378-4	
Name and address of employer for whom the thorough examination was made: PRISM LIGHTING LIMITED 5A HAMPTON INDUSTRIAL ESTATE MALPAS CHESHIRE SY14 8JQ		Address of premises at which the examination was made: PRISM LIGHTING LIMITED 5A HAMPTON INDUSTRIAL ESTATE MALPAS CHESHIRE SY14 8JQ		Our Job No: T 018669	
Description and identification of the equipment: Plant Number L10 Serial Number L-0355PJ Equipment Desc. 1 NO. ELECTRIC CHAIN HOIST MAKE: CM LOADSTAR No OF FALLS: ONE HEIGHT OF LIFT: 22M SERIAL NO: L-0355PJ PLANT NO. L10 Location PRISM		Safe working load(s): 1000KG		Date of manufacture if known: Date of last thorough examination: 13/10/2010	
Is this an examination carried out upon the supply of the Equipment? <input checked="" type="checkbox"/> NO		Was the examination carried out: Within an interval of 6 months? <input checked="" type="checkbox"/> NO		<input checked="" type="checkbox"/> YES	
Is this the first examination after installation or after assembly at a new site or location? <input checked="" type="checkbox"/> NO		Within an interval of 12 months? <input checked="" type="checkbox"/> NO		<input checked="" type="checkbox"/> YES	
If the answer to the above question is YES, has the equipment been installed correctly? <input type="checkbox"/> N/A		In accordance with an examination scheme? <input checked="" type="checkbox"/> NO		<input checked="" type="checkbox"/> NO	
After the occurrence of exceptional circumstances? <input checked="" type="checkbox"/> NO		Type of Examination \ Test Carried Out: Load Test		Examination Result \ Equipment Status: No Defects Found	
(A) Defects in Need of Attention To Prevent Immediate Failure & Details of Action Required to rectify Defects: None		(B) Defects to be Kept Under Observation, Date When Defects Must Be Rectified By and Parts Required: None		Are the above defects as stated in section (A) of Immediate Danger to Persons? <input type="checkbox"/> NO	
Particulars of Any Tests Carried Out as Part of the Examination: CALIBRATED TEST WEIGHTS 1250 KG		Additional Comments Made As Part of This Examination:		Note: Any Defect which is not yet, but could become a danger to persons as stated in section (B) above must be rectified by the date specified above in section (B).	
EQUIPMENT SAFE TO OPERATE? <input checked="" type="checkbox"/> Yes		Latest Date for Next Thorough Examination: 04 Oct 2012			

Examination Carried Out By Mercian Lifting Gear (UK) Limited Netherwood Road Rotherwas Industrial Estate Hereford HR2 6JU	Name of the person making this report: Name ALLAN PERKINS Position SERVICE ENGINEER	Name of the person authenticating this report: Name TONY BAILEY Date 06 Oct 2011 Signature 
--	---	---

Report of Thorough Examination of Lifting Equipment

This report complies with the requirements of the Lifting Operations and Lifting Equipment Regulations 1998


Date of Thorough Examination: 06 Feb 2012		Date of Report: 07 Feb 2012		Report Number: R019459-4	
Name and address of employer for whom the thorough examination was made: PRISM LIGHTING LIMITED 5A HAMPTON INDUSTRIAL ESTATE MALPAS CHESHIRE SY14 8JQ		Address of premises at which the examination was made: PRISM LIGHTING LIMITED 5A HAMPTON INDUSTRIAL ESTATE MALPAS CHESHIRE SY14 8JQ		Our Job No: T 019524	
Description and identification of the equipment: Plant Number L11 Serial Number L3339NE Equipment Desc. ELECTRIC CHAIN HOIST MODEL: CM LOADSTAR SPEED: 4 MPM HEIGHT OF LIFT: 32M Location		Safe working load(s): 1000 KGS		Date of manufacture if known: Date of last thorough examination: 01/02/2011	
Is this an examination carried out upon the supply of the Equipment? <input checked="" type="checkbox"/> NO		Was the examination carried out: Within an interval of 6 months? <input checked="" type="checkbox"/> NO		Within an interval of 12 months? <input checked="" type="checkbox"/> YES	
Is this the first examination after installation or after assembly at a new site or location? <input checked="" type="checkbox"/> NO		In accordance with an examination scheme? <input checked="" type="checkbox"/> NO		After the occurrence of exceptional circumstances? <input checked="" type="checkbox"/> NO	
If the answer to the above question is YES, has the equipment been installed correctly? <input type="checkbox"/> N/A		Type of Examination \ Test Carried Out: Load Test			
Examination Result \ Equipment Status: No Defects Found		(A) Defects In Need of Attention To Prevent Immediate Failure & Details of Action Required to rectify Defects: None			
(B) Defects to be Kept Under Observation, Date When Defects Must Be Rectified By and Parts Required: None		Are the above defects as stated in section (A) of Immediate Danger to Persons? <input type="checkbox"/> NO			
Note: Any Defect which is not yet, but could become a danger to persons as stated in section (B) above must be rectified by the date specified above in section (B).					
Particulars of Any Tests Carried Out as Part of the Examination: CALIBRATED TEST WEIGHTS 1250 KG		Additional Comments Made As Part of This Examination:			
EQUIPMENT SAFE TO OPERATE? <input checked="" type="checkbox"/> Yes		Latest Date for Next Thorough Examination: 05 Feb 2013			

Examination Carried Out By Mercian Lifting Gear (UK) Limited Netherwood Road Rotherwas Industrial Estate Hereford HR2 6JU	Name of the person making this report: Name GRAHAM THOMAS Position Service Engineer	Name of the person authenticating this report: Name TONY BAILEY Date 07 Feb 2012 Signature 
--	---	---

Report of Thorough Examination of Lifting Equipment

This report complies with the requirements of the Lifting Operations and Lifting Equipment Regulations 1998


Date of Thorough Examination: 06 Feb 2012		Date of Report: 07 Feb 2012		Report Number: R019460-5	
Name and address of employer for whom the thorough examination was made: PRISM LIGHTING LIMITED 5A HAMPTON INDUSTRIAL ESTATE MALPAS CHESHIRE SY14 8JQ		Address of premises at which the examination was made: PRISM LIGHTING LIMITED 5A HAMPTON INDUSTRIAL ESTATE MALPAS CHESHIRE SY14 8JQ		Our Job No: T 019524	
Description and identification of the equipment: Plant Number L12 Serial Number L3338NE Equipment Desc. ELECTRIC CHAIN HOIST MODEL: CM LOADSTAR SPEED: 4 MPM HEIGHT OF LIFT: 32M Location		Safe working load(s): 1000 KG	Date of manufacture if known:	Date of last thorough examination: 01/02/2011	
Is this an examination carried out upon the supply of the Equipment? <input checked="" type="checkbox"/> NO		Was the examination carried out: Within an interval of 6 months? <input checked="" type="checkbox"/> NO		<input checked="" type="checkbox"/> YES	
Is this the first examination after installation or after assembly at a new site or location? <input checked="" type="checkbox"/> NO		Within an interval of 12 months? <input checked="" type="checkbox"/> NO		<input checked="" type="checkbox"/> YES	
If the answer to the above question is YES, has the equipment been installed correctly? <input type="checkbox"/> N/A		In accordance with an examination scheme? <input checked="" type="checkbox"/> NO		<input checked="" type="checkbox"/> NO	
After the occurrence of exceptional circumstances? <input checked="" type="checkbox"/> NO					
Type of Examination \ Test Carried Out: Load Test		Examination Result \ Equipment Status: No Defects Found			
(A) Defects In Need of Attention To Prevent Immediate Failure & Details of Action Required to rectify Defects: None		(B) Defects to be Kept Under Observation, Date When Defects Must Be Rectified By and Parts Required: None			
Are the above defects as stated in section (A) of Immediate Danger to Persons? Note: Any Defect which is not yet, but could become a danger to persons as stated in section (B) above must be rectified by the date specified above in section (B).					<input type="checkbox"/> NO
Particulars of Any Tests Carried Out as Part of the Examination: CALIBRATED TEST WEIGHTS 1250 KG		Additional Comments Made As Part of This Examination:			
EQUIPMENT SAFE TO OPERATE? <input checked="" type="checkbox"/> Yes		Latest Date for Next Thorough Examination: 05 Feb 2013			

Examination Carried Out By Mercian Lifting Gear (UK) Limited Netherwood Road Rotherwas Industrial Estate Hereford HR2 6JU	Name of the person making this report: Name GRAHAM THOMAS Position Service Engineer	Name of the person authenticating this report: Name TONY BAILEY Date 07 Feb 2012 Signature 
--	---	---

Report of Thorough Examination of Lifting Equipment

This report complies with the requirements of the Lifting Operations and Lifting Equipment Regulations 1998


Date of Thorough Examination: 09 Feb 2012		Date of Report: 10 Feb 2012		Report Number: R019493-13	
Name and address of employer for whom the thorough examination was made: PRISM LIGHTING LIMITED 5A HAMPTON INDUSTRIAL ESTATE MALPAS CHESHIRE SY14 8JQ		Address of premises at which the examination was made: PRISM LIGHTING LIMITED 5A HAMPTON INDUSTRIAL ESTATE MALPAS CHESHIRE SY14 8JQ		Our Job No: T 019524	
Description and identification of the equipment. Plant Number L13 Serial Number L3332NE Equipment Desc. ELECTRIC CHAIN HOIST MODEL : CM LODESTAR SPEED 4MPM HEIGHT OF LIFT : 20M Location		Safe working load(s): 1000 KG	Date of manufacture if known:	Date of last thorough examination: 01/02/2011	
Is this an examination carried out upon the supply of the Equipment? <input checked="" type="checkbox"/> NO		Was the examination carried out: Within an interval of 6 months? <input checked="" type="checkbox"/> NO		Date of last thorough examination: 01/02/2011	
Is this the first examination after installation or after assembly at a new site or location? <input checked="" type="checkbox"/> NO		Within an interval of 12 months? <input checked="" type="checkbox"/> YES			
If the answer to the above question is YES, has the equipment been installed correctly? <input type="checkbox"/> N/A		In accordance with an examination scheme? <input checked="" type="checkbox"/> NO			
		After the occurrence of exceptional circumstances? <input checked="" type="checkbox"/> NO			
Type of Examination \ Test Carried Out: Load Test		Examination Result \ Equipment Status: No Defects Found			
(A) Defects in Need of Attention To Prevent Immediate Failure & Details of Action Required to rectify Defects: None		(B) Defects to be Kept Under Observation, Date When Defects Must Be Rectified By and Parts Required: None			
Are the above defects as stated in section (A) of Immediate Danger to Persons? Note: Any Defect which is not yet, but could become a danger to persons as stated in section (B) above must be rectified by the date specified above in section (B).					<input type="checkbox"/> NO
Particulars of Any Tests Carried Out as Part of the Examination: CALIBRATED TEST WEIGHTS 1250 KG		Additional Comments Made As Part of The Examination:			
EQUIPMENT SAFE TO OPERATE? <input checked="" type="checkbox"/> Yes		Latest Date for Next Thorough Examination: 08 Feb 2013			

Examination Carried Out By Merclan Lifting Gear (UK) Limited Netherwood Road Rotherwas Industrial Estate Hereford HR2 6JU	Name of the person making this report: Name GRAHAM THOMAS Position Service Engineer	Name of the person authenticating this report: Name TONY BAILEY Date 10 Feb 2012 Signature 
--	---	---

Report of Thorough Examination of Lifting Equipment

This report complies with the requirements of the Lifting Operations and Lifting Equipment Regulations 1998


Date of Thorough Examination: 09 Feb 2012		Date of Report: 09 Feb 2012		Report Number: R019474-10	
Name and address of employer for whom the thorough examination was made: PRISM LIGHTING LIMITED 5A HAMPTON INDUSTRIAL ESTATE MALPAS CHESHIRE SY14 8JQ		Address of premises at which the examination was made: PRISM LIGHTING LIMITED 5A HAMPTON INDUSTRIAL ESTATE MALPAS CHESHIRE SY14 8JQ		Our Job No: T 019524	
Description and identification of the equipment: Plant Number L14 Serial Number L3331NE Equipment Desc. ELECTRIC CHAIN HOIST MODEL: CM LOADSTAR SPEED: 4 MPM HEIGHT OF LIFT: 20M Location		Safe working load(s): 1000 KG		Date of manufacture if known: Date of last thorough examination: 01/02/2011	
Is this an examination carried out upon the supply of the Equipment? <input checked="" type="checkbox"/> NO		Was the examination carried out: Within an interval of 6 months? <input checked="" type="checkbox"/> NO		<input checked="" type="checkbox"/> YES	
Is this the first examination after installation or after assembly at a new site or location? <input checked="" type="checkbox"/> NO		Within an interval of 12 months? <input checked="" type="checkbox"/> NO		<input checked="" type="checkbox"/> YES	
If the answer to the above question is YES, has the equipment been installed correctly? <input type="checkbox"/> N/A		In accordance with an examination scheme? <input checked="" type="checkbox"/> NO		<input checked="" type="checkbox"/> NO	
After the occurrence of exceptional circumstances? <input checked="" type="checkbox"/> NO					
Type of Examination \ Test Carried Out: Load Test		Examination Result \ Equipment Status: No Defects Found			
(A) Defects In Need of Attention To Prevent Immediate Failure & Details of Action Required to rectify Defects: None		(B) Defects to be Kept Under Observation, Date When Defects Must Be Rectified By and Parts Required: None			
Are the above defects as stated in section (A) of Immediate Danger to Persons? Note: Any Defect which is not yet, but could become a danger to persons as stated in section (B) above must be rectified by the date specified above in section (B).					<input type="checkbox"/> NO
Particulars of Any Tests Carried Out as Part of the Examination: CALIBRATED TEST WEIGHTS 1250 KG		Additional Comments Made As Part of This Examination:			
EQUIPMENT SAFE TO OPERATE? <input checked="" type="checkbox"/> Yes		Latest Date for Next Thorough Examination: 08 Feb 2013			

Examination Carried Out By Mercian Lifting Gear (UK) Limited Netherwood Road Rotherwas Industrial Estate Hereford HR2 6JU	Name of the person making this report: Name GRAHAM THOMAS Position Service Engineer	Name of the person authenticating this report: Name TONY BAILEY Date 09 Feb 2012 Signature 
--	---	---

Report of Thorough Examination of Lifting Equipment

This report complies with the requirements of the Lifting Operations and Lifting Equipment Regulations 1998


Date of Thorough Examination: 09 Feb 2012		Date of Report: 09 Feb 2012		Report Number: R019470-6	
Name and address of employer for whom the thorough examination was made: PRISM LIGHTING LIMITED 5A HAMPTON INDUSTRIAL ESTATE MALPAS CHESHIRE SY14 8JQ		Address of premises at which the examination was made: PRISM LIGHTING LIMITED 5A HAMPTON INDUSTRIAL ESTATE MALPAS CHESHIRE SY14 8JQ		Our Job No: T 019524	
Description and identification of the equipment: Plant Number 2 Serial Number 9160179H Equipment Desc. ELECTRIC CHAIN HOIST TYPE: VERLINDE LITACHAIN HEIGHT OF LIFT: 22M Location		Safe working load(s): 1000 KGS	Date of manufacture if known:	Date of last thorough examination: 04/02/2011	
Is this an examination carried out upon the supply of the Equipment? <input checked="" type="checkbox"/> NO		Was the examination carried out: Within an interval of 6 months? <input checked="" type="checkbox"/> NO		Within an interval of 12 months? <input checked="" type="checkbox"/> YES	
Is this the first examination after installation or after assembly at a new site or location? <input checked="" type="checkbox"/> NO		In accordance with an examination scheme? <input checked="" type="checkbox"/> NO		After the occurrence of exceptional circumstances? <input checked="" type="checkbox"/> NO	
If the answer to the above question is YES, has the equipment been installed correctly? <input type="checkbox"/> N/A		Type of Examination \ Test Carried Out: Load Test			
Examination Result \ Equipment Status: No Defects Found		(A) Defects in Need of Attention To Prevent Immediate Failure & Details of Action Required to rectify Defects: None			
(B) Defects to be Kept Under Observation, Date When Defects Must Be Rectified By and Parts Required: None		Are the above defects as stated in section (A) of Immediate Danger to Persons? <input type="checkbox"/> NO Note: Any Defect which is not yet, but could become a danger to persons as stated in section (B) above must be rectified by the date specified above in section (B).			
Particulars of Any Tests Carried Out as Part of the Examination: CALIBRATED TEST WEIGHTS 1250 KG		Additional Comments Made As Part of This Examination:			
EQUIPMENT SAFE TO OPERATE? <input checked="" type="checkbox"/> Yes		Latest Date for Next Thorough Examination: 08 Feb 2013			

Examination Carried Out By Mercian Lifting Gear (UK) Limited Netherwood Road Rotherwas Industrial Estate Hereford HR2 6JU	Name of the person making this report: Name GRAHAM THOMAS Position Service Engineer	Name of the person authenticating this report: Name TONY BAILEY Date 09 Feb 2012 Signature 
--	---	---

Report of Thorough Examination of Lifting Equipment

This report complies with the requirements of the Lifting Operations and Lifting Equipment Regulations 1998


Date of Thorough Examination: 06 Oct 2011		Date of Report: 06 Oct 2011		Report Number: R018392-7	
Name and address of employer for whom the thorough examination was made: PRISM LIGHTING LIMITED 5A HAMPTON INDUSTRIAL ESTATE MALPAS CHESHIRE SY14 8JQ		Address of premises at which the examination was made: PRISM LIGHTING LIMITED 5A HAMPTON INDUSTRIAL ESTATE MALPAS CHESHIRE SY14 8JQ		Our Job No: T 018669	
Description and identification of the equipment: Plant Number NO. 5 Serial Number 9060238H Equipment Desc. ELECTRIC CHAIN HOIST MAKE : VERLINDE LITACHAIN 2 SINGLE FALL HEIGHT OF LIFT : 18M Location PRISM		Safe working load(s): 1000 KGS	Date of manufacture if known:	Date of last thorough examination: 14/10/2010	
Is this an examination carried out upon the supply of the Equipment? <input checked="" type="checkbox"/> NO		Was the examination carried out: Within an interval of 6 months? <input checked="" type="checkbox"/> NO		<input checked="" type="checkbox"/> YES	
Is this the first examination after installation or after assembly at a new site or location? <input checked="" type="checkbox"/> NO		Within an interval of 12 months? <input checked="" type="checkbox"/> NO		<input checked="" type="checkbox"/> YES	
If the answer to the above question is YES, has the equipment been installed correctly? <input type="checkbox"/> N/A		In accordance with an examination scheme? <input checked="" type="checkbox"/> NO		<input checked="" type="checkbox"/> NO	
After the occurrence of exceptional circumstances? <input checked="" type="checkbox"/> NO					
Type of Examination \ Test Carried Out: Load Test		Examination Result \ Equipment Status: No Defects Found			
(A) Defects In Need of Attention To Prevent Immediate Failure & Details of Action Required to rectify Defects: None		(B) Defects to be Kept Under Observation, Date When Defects Must Be Rectified By and Parts Required: None			
Are the above defects as stated in section (A) of Immediate Danger to Persons? Note: Any Defect which is not yet, but could become a danger to persons as stated in section (B) above must be rectified by the date specified above in section (B).					<input type="checkbox"/> NO
Particulars of Any Tests Carried Out as Part of the Examination: CALIBRATED TEST WEIGHTS 1250 KG		Additional Comments Made As Part of This Examination:			
EQUIPMENT SAFE TO OPERATE? <input checked="" type="checkbox"/> Yes		Latest Date for Next Thorough Examination: 05 Oct 2012			

Examination Carried Out By Mercian Lifting Gear (UK) Limited Netherwood Road Rotherwas Industrial Estate Hereford HR2 6JU	Name of the person making this report: Name NIGEL PREECE Position Service Engineer	Name of the person authenticating this report: Name TONY BAILEY Date 06 Oct 2011 Signature 
--	--	---

Report of Thorough Examination of Lifting Equipment

This report complies with the requirements of the Lifting Operations and Lifting Equipment Regulations 1998


Date of Thorough Examination: 06 Oct 2011		Date of Report: 06 Oct 2011		Report Number: R018393-8	
Name and address of employer for whom the thorough examination was made: PRISM LIGHTING LIMITED 5A HAMPTON INDUSTRIAL ESTATE MALPAS CHESHIRE SY14 8JQ		Address of premises at which the examination was made: PRISM LIGHTING LIMITED 5A HAMPTON INDUSTRIAL ESTATE MALPAS CHESHIRE SY14 8JQ		Our Job No: T 018669	
Description and identification of the equipment: Plant Number NO. 6 Serial Number 9160803H Equipment Desc. ELECTRIC CHAIN HOIST MAKE : VERLINDE LITACHAIN 2 SINGLE FALL HEIGHT OF LIFT : 18M Location PRISM		Safe working load(s): 1000 KGS	Date of manufacture if known:	Date of last thorough examination: 14/10/2010	
Is this an examination carried out upon the supply of the Equipment? <input checked="" type="checkbox"/> NO		Was the examination carried out: Within an interval of 6 months? <input checked="" type="checkbox"/> NO		<input checked="" type="checkbox"/> YES	
Is this the first examination after installation or after assembly at a new site or location? <input checked="" type="checkbox"/> NO		Within an interval of 12 months? <input checked="" type="checkbox"/> NO		<input checked="" type="checkbox"/> YES	
If the answer to the above question is YES, has the equipment been installed correctly? <input type="checkbox"/> N/A		In accordance with an examination scheme? <input checked="" type="checkbox"/> NO		<input checked="" type="checkbox"/> NO	
Type of Examination \ Test Carried Out: Load Test		Examination Result \ Equipment Status: No Defects Found			
(A) Defects In Need of Attention To Prevent Immediate Failure & Details of Action Required to rectify Defects: None		(B) Defects to be Kept Under Observation, Date When Defects Must Be Rectified By and Parts Required: None			
Are the above defects as stated in section (A) of Immediate Danger to Persons? Note: Any Defect which is not yet, but could become a danger to persons as stated in section (B) above must be rectified by the date specified above in section (B).		<input type="checkbox"/> NO			
Particulars of Any Tests Carried Out as Part of the Examination: CALIBRATED TEST WEIGHTS 1250 KG		Additional Comments Made As Part of This Examination:			
EQUIPMENT SAFE TO OPERATE? <input checked="" type="checkbox"/> Yes		Latest Date for Next Thorough Examination: 05 Oct 2012			

Examination Carried Out By Mercian Lifting Gear (UK) Limited Netherwood Road Rotherwas Industrial Estate Hereford HR2 6JU	Name of the person making this report: Name NIGEL PREECE Position Service Engineer	Name of the person authenticating this report: Name TONY BAILEY Date 06 Oct 2011 Signature 
--	--	---

Report of Thorough Examination of Lifting Equipment

This report complies with the requirements of the Lifting Operations and Lifting Equipment Regulations 1998


Date of Thorough Examination: 06 Oct 2011		Date of Report: 06 Oct 2011		Report Number: R018394-9	
Name and address of employer for whom the thorough examination was made: PRISM LIGHTING LIMITED 5A HAMPTON INDUSTRIAL ESTATE MALPAS CHESHIRE SY14 8JQ		Address of premises at which the examination was made: PRISM LIGHTING LIMITED 5A HAMPTON INDUSTRIAL ESTATE MALPAS CHESHIRE SY14 8JQ		Our Job No: T 018669	
Description and identification of the equipment: Plant Number NO. 7 Serial Number 9160742H Equipment Desc. ELECTRIC CHAIN HOIST MAKE : VERLINDE LITACHAIN 2 SINGLE FALL Location PRISM		Safe working load(s): 1000 KGS	Date of manufacture if known:	Date of last thorough examination: 14/10/2010	
Is this an examination carried out upon the supply of the Equipment? <input checked="" type="checkbox"/> NO		Was the examination carried out: Within an interval of 6 months? <input checked="" type="checkbox"/> NO		<input checked="" type="checkbox"/> YES	
Is this the first examination after installation or after assembly at a new site or location? <input checked="" type="checkbox"/> NO		Within an interval of 12 months? <input checked="" type="checkbox"/> NO		<input checked="" type="checkbox"/> YES	
If the answer to the above question is YES, has the equipment been installed correctly? <input type="checkbox"/> N/A		In accordance with an examination scheme? <input checked="" type="checkbox"/> NO		<input checked="" type="checkbox"/> NO	
After the occurrence of exceptional circumstances? <input checked="" type="checkbox"/> NO					
Type of Examination \ Test Carried Out: Load Test		Examination Result \ Equipment Status: No Defects Found			
(A) Defects In Need of Attention To Prevent Immediate Failure & Details of Action Required to rectify Defects: None		(B) Defects to be Kept Under Observation, Date When Defects Must Be Rectified By and Parts Required: None			
Are the above defects as stated in section (A) of Immediate Danger to Persons? Note: Any Defect which is not yet, but could become a danger to persons as stated in section (B) above must be rectified by the date specified above in section (B).					<input type="checkbox"/> NO
Particulars of Any Tests Carried Out as Part of the Examination: CALIBRATED TEST WEIGHTS 1250 KG		Additional Comments Made As Part of This Examination:			
EQUIPMENT SAFE TO OPERATE? <input checked="" type="checkbox"/> Yes		Latest Date for Next Thorough Examination: 05 Oct 2012			

Examination Carried Out By Mercian Lifting Gear (UK) Limited Netherwood Road Rotherwas Industrial Estate Hereford HR2 6JU	Name of the person making this report: Name NIGEL PREECE Position Service Engineer	Name of the person authenticating this report: Name TONY BAILEY Date 06 Oct 2011 Signature 
--	--	---

Report of Thorough Examination of Lifting Equipment

This report complies with the requirements of the Lifting Operations and Lifting Equipment Regulations 1998


Date of Thorough Examination: 09 Feb 2012		Date of Report: 09 Feb 2012		Report Number: R019471-7	
Name and address of employer for whom the thorough examination was made: PRISM LIGHTING LIMITED 5A HAMPTON INDUSTRIAL ESTATE MALPAS CHESHIRE SY14 8JQ		Address of premises at which the examination was made: PRISM LIGHTING LIMITED 5A HAMPTON INDUSTRIAL ESTATE MALPAS CHESHIRE SY14 8JQ		Our Job No: T 019524	
Description and identification of the equipment: Plant Number 8 Serial Number 9160694H Equipment Desc. ELECTRIC CHAIN HOIST TYPE: VERLINDE LITACHAIN HEIGHT OF LIFT: 20M Location		Safe working load(s): 1000 KGS		Date of manufacture if known: Date of last thorough examination: 04/02/2011	
Is this an examination carried out upon the supply of the Equipment? <input checked="" type="checkbox"/> NO		Was the examination carried out: Within an interval of 6 months? <input checked="" type="checkbox"/> NO		Within an interval of 12 months? <input checked="" type="checkbox"/> YES	
Is this the first examination after installation or after assembly at a new site or location? <input checked="" type="checkbox"/> NO		In accordance with an examination scheme? <input checked="" type="checkbox"/> NO		After the occurrence of exceptional circumstances? <input checked="" type="checkbox"/> NO	
If the answer to the above question is YES, has the equipment been installed correctly? <input type="checkbox"/> N/A		Type of Examination \ Test Carried Out: Load Test			
Examination Result \ Equipment Status: No Defects Found		(A) Defects In Need of Attention To Prevent Immediate Failure & Details of Action Required to rectify Defects: None			
(B) Defects to be Kept Under Observation, Date When Defects Must Be Rectified By and Parts Required: None		Are the above defects as stated in section (A) of Immediate Danger to Persons? <input type="checkbox"/> NO			
Note: Any Defect which is not yet, but could become a danger to persons as stated in section (B) above must be rectified by the date specified above in section (B).					
Particulars of Any Tests Carried Out as Part of the Examination: CALIBRATED TEST WEIGHTS 1250 KG		Additional Comments Made As Part of This Examination:			
EQUIPMENT SAFE TO OPERATE? <input checked="" type="checkbox"/> Yes		Latest Date for Next Thorough Examination: 08 Feb 2013			

Examination Carried Out By Mercian Lifting Gear (UK) Limited Netherwood Road Rotherwas Industrial Estate Hereford HR2 6JU	Name of the person making this report: Name GRAHAM THOMAS Position Service Engineer	Name of the person authenticating this report: Name TONY BAILEY Date 09 Feb 2012 Signature 
--	---	--

Report of Thorough Examination of Lifting Equipment

This report complies with the requirements of the Lifting Operations and Lifting Equipment Regulations 1998


Date of Thorough Examination: 06 Oct 2011		Date of Report: 06 Oct 2011		Report Number: R018395-10	
Name and address of employer for whom the thorough examination was made: PRISM LIGHTING LIMITED 5A HAMPTON INDUSTRIAL ESTATE MALPAS CHESHIRE SY14 8JQ		Address of premises at which the examination was made: PRISM LIGHTING LIMITED 5A HAMPTON INDUSTRIAL ESTATE MALPAS CHESHIRE SY14 8JQ		Our Job No: T 018669	
Description and identification of the equipment: Plant Number NO. 11 Serial Number 9661584 Equipment Desc. ELECTRIC CHAIN HOIST MAKE : VERLINDE LITACHAIN 2 SINGLE FALL HEIGHT OF LIFT : 18M Location PRISM		Safe working load(s): 1000 KGS	Date of manufacture if known:	Date of last thorough examination: 15/10/2010	
Is this an examination carried out upon the supply of the Equipment? <input checked="" type="checkbox"/> NO		Was the examination carried out: Within an interval of 6 months? <input checked="" type="checkbox"/> NO		Within an interval of 12 months? <input checked="" type="checkbox"/> YES	
Is this the first examination after installation or after assembly at a new site or location? <input checked="" type="checkbox"/> NO		In accordance with an examination scheme? <input checked="" type="checkbox"/> NO		After the occurrence of exceptional circumstances? <input checked="" type="checkbox"/> NO	
If the answer to the above question is YES, has the equipment been installed correctly? <input type="checkbox"/> N/A		Type of Examination/Test Carried Out: Load Test			
Examination Result \ Equipment Status: No Defects Found		(A) Defects In Need of Attention To Prevent Immediate Failure & Details of Action Required to rectify Defects: None			
(B) Defects to be Kept Under Observation, Date When Defects Must Be Rectified By and Parts Required: None		Are the above defects as stated in section (A) of Immediate Danger to Persons? <input type="checkbox"/> NO			
Note: Any Defect which is not yet, but could become a danger to persons as stated in section (B) above must be rectified by the date specified above in section (B).					
Particulars of Any Tests Carried Out as Part of the Examination: CALIBRATED TEST WEIGHTS 1250 KG		Additional Comments Made As Part of This Examination:			
EQUIPMENT SAFE TO OPERATE? <input checked="" type="checkbox"/> Yes		Latest Date for Next Thorough Examination: 05 Oct 2012			

Examination Carried Out By Mercian Lifting Gear (UK) Limited Netherwood Road Rotherwas Industrial Estate Hereford HR2 6JU	Name of the person making this report: Name NIGEL PREECE Position Service Engineer	Name of the person authenticating this report: Name TONY BAILEY Date 06 Oct 2011 Signature 
--	--	---

Report of Thorough Examination of Lifting Equipment

This report complies with the requirements of the Lifting Operations and Lifting Equipment Regulations 1998


Date of Thorough Examination: 06 Oct 2011		Date of Report: 06 Oct 2011		Report Number: R018396-11	
Name and address of employer for whom the thorough examination was made: PRISM LIGHTING LIMITED 5A HAMPTON INDUSTRIAL ESTATE MALPAS CHESHIRE SY14 8JQ		Address of premises at which the examination was made: PRISM LIGHTING LIMITED 5A HAMPTON INDUSTRIAL ESTATE MALPAS CHESHIRE SY14 8JQ		Our Job No: T 018669	
Description and identification of the equipment: Plant Number NO. 12 Serial Number 9661586 Equipment Desc. ELECTRIC CHAIN HOIST MAKE : VERLINDE LITACHAIN HEIGHT OF LIFT : 18M Location PRISM		Safe working load(s): 1000 KGS	Date of manufacture if known:	Date of last thorough examination: 15/10/2010	
Is this an examination carried out upon the supply of the Equipment? <input checked="" type="checkbox"/> NO		Was the examination carried out: Within an interval of 6 months? <input checked="" type="checkbox"/> NO		<input checked="" type="checkbox"/> NO	
Is this the first examination after installation or after assembly at a new site or location? <input checked="" type="checkbox"/> NO		Within an interval of 12 months? <input checked="" type="checkbox"/> YES		<input checked="" type="checkbox"/> YES	
If the answer to the above question is YES, has the equipment been installed correctly? <input type="checkbox"/> N/A		In accordance with an examination scheme? <input checked="" type="checkbox"/> NO		<input checked="" type="checkbox"/> NO	
Type of Examination/Test Carried Out: Test Not Selected !!!		Examination Result \ Equipment Status: No Defects Found			
(A) Defects In Need of Attention To Prevent Immediate Failure & Details of Action Required to rectify Defects: None		(B) Defects to be Kept Under Observation, Date When Defects Must Be Rectified By and Parts Required: None			
Are the above defects as stated in section (A) of Immediate Danger to Persons? Note: Any Defect which is not yet, but could become a danger to persons as stated in section (B) above must be rectified by the date specified above in section (B).					<input type="checkbox"/> NO
Particulars of Any Tests Carried Out as Part of the Examination: CALIBRATED TEST WEIGHTS 1250 KG		Additional Comments Made As Part of This Examination:			
EQUIPMENT SAFE TO OPERATE? <input checked="" type="checkbox"/> Yes		Latest Date for Next Thorough Examination: 05 Oct 2012			

Examination Carried Out By Mercian Lifting Gear (UK) Limited Netherwood Road Rotherwas Industrial Estate Hereford HR2 6JU	Name of the person making this report: Name NIGEL PREECE Position Service Engineer	Name of the person authenticating this report: Name TONY BAILEY Date 06 Oct 2011 Signature 
--	--	---

Report of Thorough Examination of Lifting Equipment

This report complies with the requirements of the Lifting Operations and Lifting Equipment Regulations 1998


Date of Thorough Examination: 09 Feb 2012		Date of Report: 09 Feb 2012		Report Number: R019475-11	
Name and address of employer for whom the thorough examination was made: PRISM LIGHTING LIMITED 5A HAMPTON INDUSTRIAL ESTATE MALPAS CHESHIRE SY14 8JQ		Address of premises at which the examination was made: PRISM LIGHTING LIMITED 5A HAMPTON INDUSTRIAL ESTATE MALPAS CHESHIRE SY14 8JQ		Our Job No: T 019524	
Description and identification of the equipment: Plant Number RR1 Serial Number 2392 NX Equipment Desc. ELECTRIC CHAIN HOIST MAKE : CM LOADSTAR HEIGHT OF LIFT : 20M Location		Safe working load(s): 2 TON	Date of manufacture if known:	Date of last thorough examination: 04/02/2011	
Is this an examination carried out upon the supply of the Equipment? <input checked="" type="checkbox"/> NO		Was the examination carried out: Within an interval of 6 months? <input checked="" type="checkbox"/> NO		Within an interval of 12 months? <input checked="" type="checkbox"/> YES	
Is this the first examination after installation or after assembly at a new site or location? <input checked="" type="checkbox"/> NO		In accordance with an examination scheme? <input checked="" type="checkbox"/> NO		After the occurrence of exceptional circumstances? <input checked="" type="checkbox"/> NO	
If the answer to the above question is YES, has the equipment been installed correctly? <input type="checkbox"/> N/A					
Type of Examination \ Test Carried Out: Load Test		Examination Result \ Equipment Status: No Defects Found			
(A) Defects In Need of Attention To Prevent Immediate Failure & Details of Action Required to rectify Defects: None		(B) Defects to be Kept Under Observation, Date When Defects Must Be Rectified By and Parts Required: None			
Are the above defects as stated in section (A) of Immediate Danger to Persons? Note: Any Defect which is not yet, but could become a danger to persons as stated in section (B) above must be rectified by the date specified above in section (B).		<input type="checkbox"/> NO			
Particulars of Any Tests Carried Out as Part of the Examination: CALIBRATED TEST WEIGHTS 2500 KG		Additional Comments Made As Part of This Examination:			
EQUIPMENT SAFE TO OPERATE? <input checked="" type="checkbox"/> Yes		Latest Date for Next Thorough Examination: 08 Feb 2013			

Examination Carried Out By Mercian Lifting Gear (UK) Limited Netherwood Road Rotherwas Industrial Estate Hereford HR2 6JU	Name of the person making this report: Name GRAHAM THOMAS Position Service Engineer	Name of the person authenticating this report: Name TONY BAILEY Date 09 Feb 2012 Signature 
--	---	---

Report of Thorough Examination of Lifting Equipment

This report complies with the requirements of the Lifting Operations and Lifting Equipment Regulations 1998


Date of Thorough Examination: 09 Feb 2012		Date of Report: 09 Feb 2012		Report Number: R019476-12	
Name and address of employer for whom the thorough examination was made: PRISM LIGHTING LIMITED 5A HAMPTON INDUSTRIAL ESTATE MALPAS CHESHIRE SY14 8JQ			Address of premises at which the examination was made: PRISM LIGHTING LIMITED 5A HAMPTON INDUSTRIAL ESTATE MALPAS CHESHIRE SY14 8JQ		Our Job No: T 019524
Description and identification of the equipment: Plant Number RR2 Serial Number 2389 NX Equipment Desc. ELECTRIC CHAIN HOIST MAKE : CM LOADSTAR HEIGHT OF LIFT : 20M Location			Safe working load(s): 2 TON	Date of manufacture if known:	Date of last thorough examination: 04/02/2011
Is this an examination carried out upon the supply of the Equipment? <input checked="" type="checkbox"/> NO			Was the examination carried out: Within an interval of 6 months? <input checked="" type="checkbox"/> NO		
Is this the first examination after installation or after assembly at a new site or location? <input checked="" type="checkbox"/> NO			Within an interval of 12 months? <input checked="" type="checkbox"/> YES		
If the answer to the above question is YES, has the equipment been installed correctly? <input type="checkbox"/> N/A			In accordance with an examination scheme? <input checked="" type="checkbox"/> NO		
Type of Examination \ Test Carried Out: Load Test			After the occurrence of exceptional circumstances? <input checked="" type="checkbox"/> NO		
(A) Defects In Need of Attention To Prevent Immediate Failure & Details of Action Required to rectify Defects: None			Examination Result \ Equipment Status: No Defects Found		
Are the above defects as stated in section (A) of Immediate Danger to Persons? Note: Any Defect which is not yet, but could become a danger to persons as stated in section (B) above must be rectified by the date specified above in section (B).			(B) Defects to be Kept Under Observation, Date When Defects Must Be Rectified By and Parts Required: None		
Particulars of Any Tests Carried Out as Part of the Examination: CALIBRATED TEST WEIGHTS 2500 KG			Additional Comments Made As Part of This Examination: <input type="checkbox"/> NO		
EQUIPMENT SAFE TO OPERATE? <input checked="" type="checkbox"/> Yes			Latest Date for Next Thorough Examination: 08 Feb 2013		

Examination Carried Out By Mercian Lifting Gear (UK) Limited Netherwood Road Rotherwas Industrial Estate Hereford HR2 6JU	Name of the person making this report: Name GRAHAM THOMAS Position Service Engineer	Name of the person authenticating this report: Name TONY BAILEY Date 09 Feb 2012 Signature 
--	---	---

Report of Thorough Examination of Lifting Equipment

This report complies with the requirements of the Lifting Operations and Lifting Equipment Regulations 1998

Date of Thorough Examination: 05 Oct 2011		Date of Report: 06 Oct 2011		Report Number: R018379-5	
Name and address of employer for whom the thorough examination was made: PRISM LIGHTING LIMITED 5A HAMPTON INDUSTRIAL ESTATE MALPAS CHESHIRE SY14 8JQ		Address of premises at which the examination was made: PRISM LIGHTING LIMITED 5A HAMPTON INDUSTRIAL ESTATE MALPAS CHESHIRE SY14 8JQ		Our Job No: T 018669	
Description and identification of the equipment: Plant Number F1 Serial Number L2291 NX Equipment Desc. 1 NO. ELECTRIC CHAIN HOIST MAKE : CM LODESTAR HEIGHT OF LIFT : 20M SERIAL NO. L2291 NX PLANT NO. F1 Location PRISM		Safe working load(s): 500 KG		Date of manufacture if known: Date of last thorough examination: 14/10/2010	
Is this an examination carried out upon the supply of the Equipment? <input checked="" type="checkbox"/> NO		Was the examination carried out: Within an interval of 6 months? <input checked="" type="checkbox"/> NO		Is this the first examination after installation or after assembly at a new site or location? <input checked="" type="checkbox"/> NO	
If the answer to the above question is YES, has the equipment been installed correctly? <input type="checkbox"/> N/A		Within an interval of 12 months? <input checked="" type="checkbox"/> YES		In accordance with an examination scheme? <input checked="" type="checkbox"/> NO	
		After the occurrence of exceptional circumstances? <input checked="" type="checkbox"/> NO			
Type of Examination \ Test Carried Out: Load Test		Examination Result \ Equipment Status: No Defects Found			
(A) Defects In Need of Attention To Prevent Immediate Failure & Details of Action Required to rectify Defects: None		(B) Defects to be Kept Under Observation, Date When Defects Must Be Rectified By and Parts Required: None			
Are the above defects as stated in section (A) of Immediate Danger to Persons? Note: Any Defect which is not yet, but could become a danger to persons as stated in section (B) above must be rectified by the date specified above in section (B).					<input type="checkbox"/> NO
Particulars of Any Tests Carried Out as Part of the Examination: CALIBRATED TEST WEIGHTS 625 KG		Additional Comments Made As Part of This Examination:			
EQUIPMENT SAFE TO OPERATE? <input checked="" type="checkbox"/> Yes		Latest Date for Next Thorough Examination: 04 Oct 2012			

Examination Carried Out By Mercian Lifting Gear (UK) Limited Netherwood Road Rotherwas Industrial Estate Hereford HR2 6JU	Name of the person making this report: Name ALLAN PERKINS Position SERVICE ENGINEER	Name of the person authenticating this report: Name TONY BAILEY Date 06 Oct 2011 Signature 
---	--	---

Report of Thorough Examination of Lifting Equipment

This report complies with the requirements of the Lifting Operations and Lifting Equipment Regulations 1998

Date of Thorough Examination: 05 Oct 2011	Date of Report: 06 Oct 2011	Report Number: R018380-6
--	------------------------------------	---------------------------------

Name and address of employer for whom the thorough examination was made: PRISM LIGHTING LIMITED 5A HAMPTON INDUSTRIAL ESTATE MALPAS CHESHIRE SY14 8JQ	Address of premises at which the examination was made: PRISM LIGHTING LIMITED 5A HAMPTON INDUSTRIAL ESTATE MALPAS CHESHIRE SY14 8JQ	Our Job No: T 018669
--	--	-------------------------

Description and identification of the equipment: Plant Number F2 Serial Number L2282 NX Equipment Desc. 1 NO. ELECTRIC CHAIN HOIST MAKE : CM LODESTAR HEIGHT OF LIFT : 20M SERIAL NO. L2282 NX PLANT NO. F2 Location PRISM	Safe working load(s): 500 KG	Date of manufacture if known:	Date of last thorough examination: 14/10/2010
--	---------------------------------	-------------------------------	--


Is this an examination carried out upon the supply of the Equipment? <input checked="" type="checkbox"/> NO	Was the examination carried out: Within an interval of 6 months? <input checked="" type="checkbox"/> NO
Is this the first examination after installation or after assembly at a new site or location? <input checked="" type="checkbox"/> NO	Within an interval of 12 months? <input checked="" type="checkbox"/> YES
If the answer to the above question is YES, has the equipment been installed correctly? <input type="checkbox"/> N/A	In accordance with an examination scheme? <input checked="" type="checkbox"/> NO
	After the occurrence of exceptional circumstances? <input checked="" type="checkbox"/> NO

Type of Examination \ Test Carried Out: Load Test	Examination Result \ Equipment Status: No Defects Found
(A) Defects in Need of Attention To Prevent Immediate Failure & Details of Action Required to rectify Defects: None	(B) Defects to be Kept Under Observation, Date When Defects Must Be Rectified By and Parts Required: None

Are the above defects as stated in section (A) of Immediate Danger to Persons?
Note: Any Defect which is not yet, but could become a danger to persons as stated in section (B) above must be rectified by the date specified above in section (B).
 NO

Particulars of Any Tests Carried Out as Part of the Examination: CALIBRATED TEST WEIGHTS 625 KG	Additional Comments Made As Part of This Examination:
--	---


EQUIPMENT SAFE TO OPERATE? <input checked="" type="checkbox"/> Yes	Latest Date for Next Thorough Examination: 04 Oct 2012
---	---

Examination Carried Out By Mercian Lifting Gear (UK) Limited Netherwood Road Rotherwas Industrial Estate Hereford HR2 6JU	Name of the person making this report: Name ALLAN PERKINS Position SERVICE ENGINEER	Name of the person authenticating this report: Name TONY BAILEY Date 06 Oct 2011 Signature 
--	---	---

Report of Thorough Examination of Lifting Equipment

This report complies with the requirements of the Lifting Operations and Lifting Equipment Regulations 1998


Date of Thorough Examination: 06 May 2011		Date of Report: 06 May 2011		Report Number: 016476-5	
Name and address of employer for whom the thorough examination was made: PRISM LIGHTING LIMITED 5A HAMPTON INDUSTRIAL ESTATE MALPAS CHESHIRE SY14 8JQ			Address of premises at which the examination was made: PRISM LIGHTING LIMITED 5A HAMPTON INDUSTRIAL ESTATE MALPAS CHESHIRE SY14 8JQ		
Description and identification of the equipment: Plant Number F3 Serial Number L-1005NB Equipment Desc. 1 NO. ELECTRIC CHAIN HOIST MAKE : CM LODESTAR HEIGHT OF LIFT : 30M Location		Safe working load(s): 500 KG	Date of manufacture if known:	Date of last thorough examination: 21/04/2010	
Is this an examination carried out upon the supply of the Equipment? <input checked="" type="checkbox"/> NO		Was the examination carried out: Within an interval of 6 months? <input checked="" type="checkbox"/> NO		Within an interval of 12 months? <input checked="" type="checkbox"/> YES	
Is this the first examination after installation or after assembly at a new site or location? <input checked="" type="checkbox"/> NO		In accordance with an examination scheme? <input checked="" type="checkbox"/> NO		After the occurrence of exceptional circumstances? <input checked="" type="checkbox"/> NO	
If the answer to the above question is YES, has the equipment been installed correctly? <input type="checkbox"/> N/A					
Type of Examination \ Test Carried Out: Proof Load Test		Examination Result \ Equipment Status: No Defects Found			
(A) Defects In Need of Attention To Prevent Immediate Failure & Details of Action Required to rectify Defects: None		(B) Defects to be Kept Under Observation, Date When Defects Must Be Rectified By and Parts Required: None			
Are the above defects as stated in section (A) of Immediate Danger to Persons? Note: Any Defect which is not yet, but could become a danger to persons as stated in section (B) above must be rectified by the date specified above in section (B).					<input checked="" type="checkbox"/> NO
Particulars of Any Tests Carried Out as Part of the Examination: PROOF LOAD TEST TO 625 KG			Additional Comments Made As Part of This Examination:		
EQUIPMENT SAFE TO OPERATE? <input checked="" type="checkbox"/> Yes		Latest Date for Next Thorough Examination: 07 May 2012			

Examination Carried Out By Mercian Lifting Gear (UK) Limited Netherwood Road Rotherwas Industrial Estate Hereford HR2 6JU	Name of the person making this report:		Name of the person authenticating this report:	
	Name	GRAHAM THOMAS	Name	TONY BAILEY
	Position	Service Engineer	Date	06 May 2011
			Signature	

Report of Thorough Examination of Lifting Equipment

This report complies with the requirements of the Lifting Operations and Lifting Equipment Regulations 1998

Date of Thorough Examination: 06 May 2011		Date of Report: 06 May 2011		Report Number: 016477-6	
Name and address of employer for whom the thorough examination was made: PRISM LIGHTING LIMITED 5A HAMPTON INDUSTRIAL ESTATE MALPAS CHESHIRE SY14 8JQ			Address of premises at which the examination was made: PRISM LIGHTING LIMITED 5A HAMPTON INDUSTRIAL ESTATE MALPAS CHESHIRE SY14 8JQ		
Description and identification of the equipment: Plant Number F4 Serial Number L-1006NB Equipment Desc. 1 NO. CHAIN HOIST MAKE : CM LODESTAR HEIGHT OF LIFT : 30M Location		Safe working load(s): 500 KG	Date of manufacture if known:	Date of last thorough examination: 21/04/2010	
Is this an examination carried out upon the supply of the Equipment? <input checked="" type="checkbox"/> NO		Was the examination carried out: Within an interval of 6 months? <input checked="" type="checkbox"/> NO		In accordance with an examination scheme? <input checked="" type="checkbox"/> NO	
Is this the first examination after installation or after assembly at a new site or location? <input checked="" type="checkbox"/> NO		Within an interval of 12 months? <input checked="" type="checkbox"/> YES		After the occurrence of exceptional circumstances? <input checked="" type="checkbox"/> NO	
If the answer to the above question is YES, has the equipment been installed correctly? <input type="checkbox"/> N/A		Type of Examination \ Test Carried Out: Proof Load Test			
Examination Result \ Equipment Status: No Defects Found		(A) Defects In Need of Attention To Prevent Immediate Failure & Details of Action Required to rectify Defects: None			
(B) Defects to be Kept Under Observation, Date When Defects Must Be Rectified By and Parts Required: None		Are the above defects as stated in section (A) of Immediate Danger to Persons? <input checked="" type="checkbox"/> NO			
Note: Any Defect which is not yet, but could become a danger to persons as stated in section (B) above must be rectified by the date specified above in section (B).					
Particulars of Any Tests Carried Out as Part of the Examination: PROOF LOAD TEST TO 625 KG		Additional Comments Made As Part of This Examination:			
EQUIPMENT SAFE TO OPERATE? <input checked="" type="checkbox"/> Yes		Latest Date for Next Thorough Examination: 07 May 2012			

Examination Carried Out By Mercian Lifting Gear (UK) Limited Netherwood Road Rotherwas Industrial Estate Hereford HR2 6JU	Name of the person making this report: Name GRAHAM THOMAS Position Service Engineer	Name of the person authenticating this report: Name TONY BAILEY Date 06 May 2011 Signature 
--	---	---